



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D S V50
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-02
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-07
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	23
Total items failed	3

MOT #15	2023-08-08 08:45
MOT test number	615102444560
Result	✓ Passed
Next expiry date	2024-08-07
Minor	Windscreen damaged but not adversely affecting driver's view Stone chips (2) (3.2 (a) (i))

MOT #14	2023-08-07 07:34
MOT test number	348420252000
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view Stone chips (2) (3.2 (a) (i))
DANGEROUS	Nearside Rear Anti-roll bar attachment bracket/mounting fractured (5.3.3 (b) (ii))

MOT #13	2022-07-21 11:07
MOT test number	905373086366
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Child seat fitted
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-06-26 11:42**MOT test number** 584998801316**Result** ✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing on the limit (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))
- Advice** Rear heat shield
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing on the limit (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play on the limit (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Undertrays and engine covers fitted obscuring full view of inspection
- Advice** Nearside Front Suspension arm ball joint has slight play on the limit (5.3.4 (a) (i))
- Advice** Rear hand brake low effort

MOT #11 2020-04-20 09:59**MOT test number** 216967168794**Result** ✓ Passed

- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #10 2018-10-17 10:34**MOT test number** 326431125993**Result** ✓ Passed

**MOT #9** 2017-12-21 16:12**MOT test number** 891132203029**Result** ✓ Passed**Advice** Under trays and engine covers fitted obscuring full view of inspection.**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2017-12-20 16:29**MOT test number** 215639683720**Result** ✗ Failed**Advice** Under trays and engine covers fitted obscuring full view of inspection.**Fail** Fuel system component leaking (7.2.3)**Fail** Nearside Rear Braking system leaking (3.6.A.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-10-17 11:44**MOT test number** 274191461681**Result** ✓ Passed**MOT #6** 2016-10-17 11:44**MOT test number** 477360867547**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2015-10-23 08:53**MOT test number** 309319950322**Result** ✓ Passed



MOT #4	2014-10-21 09:57
MOT test number	887724094298
Result	✓ Passed
MOT #3	2013-10-18 15:30
MOT test number	805691493290
Result	✓ Passed
MOT #2	2012-10-19 14:51
MOT test number	547543492247
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2011-10-24 17:15
MOT test number	388677591420
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-24
Last registration	2023-08-08
Complete history	See info



Registration #1	2008-10-24	14 mi
Registration #2	2011-10-24	54.899 mi
Registration #3	2012-10-19	68.005 mi
Registration #4	2013-10-18	87.574 mi
Registration #5	2014-10-21	106.269 mi
Registration #6	2015-10-23	115.561 mi
Registration #7	2016-10-17	126.545 mi
Registration #8	2016-10-17	126.545 mi
Registration #9	2017-12-20	138.423 mi
Registration #10	2018-05-22	151.377 mi
Registration #11	2018-05-22	151.377 mi
Registration #12	2018-05-22	151.377 mi
Registration #13	2018-05-22	151.377 mi
Registration #14	2018-05-22	151.377 mi
Registration #15	2018-05-22	151.377 mi
Registration #16	2018-05-22	151.377 mi
Registration #17	2018-05-22	151.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1436 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	421497