





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE 16V
Colour	Blue
Year of manufacture	2003
Top speed	121 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2021-01-17
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	15
Total items failed	8

MOT #16		2020-01-16 09:18
MOT test i	number	242526458822
Result		✓ Passed
Next expir	y date	2021-01-17
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing inner e	edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Nail in tyre	
Advice	Rear Brake hose has slight corrosion to ferrule both rear (1.1.12 (f) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice (5.2.3 (e))	Nearside Rear Tyre worn close to legal limit/worn on edge on legal limit an	d wearing outer edge

CarCheck.co.uk page 2/11



RX53CCU

report date: 2024-03-29

MOT #15	2019-01-18 15:09
MOT test number	466695038722
Result	✓ Passed
Advice Nearside Rear tyre worn low to legal limit (raised tread)	

MOT #14	2018-01-15 10:36
MOT test number	322962137232
Result	✓ Passed
MOT #13	2017-01-13 10:16
MOT test number	571896707352
Result	✓ Passed
Advice Eml on	

MOT #12	2014-12-08 09:18
MOT test number	368382744384
Result	✓ Passed
MOT #11	2013-11-28 15:14
MOT test number	755052333339
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #10	2012-11-23 10:15
MOT test number	447898722416
Result	✓ Passed
MOT #9	2011-11-23 11:59
MOT test number	916707121329
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

RX53CCU report date: 2024-03-29

X Failed

MOT #8 2011-11-22 09:14

MOT test number 728846521371

Result X Failed

Fail Offside Front constant velocity joint is insecure (2.5.C.1b)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #7 2011-10-03 11:57

MOT test number 645986471248

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

Fail Offside Front Front constant velocity joint gaiter split (2.5.C.1a)

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #6 2010-09-08 11:17

MOT test number 211851150222

Result
✓ Passed

MOT #5 2010-09-07 15:12

MOT test number 733080850268

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4 2009-06-10 14:56

MOT test number 293121769499

Result

Passed

CarCheck.co.uk page 4/11



MOT #3 2008-05-06 12:53

MOT test number 960827528122

Result
✓ Passed

MOT #2 2007-10-01 12:25

MOT test number 744644077247

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2006-09-14 15:45

MOT test number 703977156221

CarCheck.co.uk page 5/11



RX53CCU

report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	AIN
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2003-09-15
Last registration	2020-01-16
Complete history	See info



Registration #1	2003-09-15	23 mi
Registration #2	2006-09-14	22.021 mi
Registration #3	2007-10-01	26.366 mi
Registration #4	2008-05-06	28.761 mi
Registration #5	2009-06-10	34.261 mi
Registration #6	2010-09-07	39.810 mi
Registration #7	2010-09-08	39.810 mi
Registration #8	2011-10-03	42.609 mi
Registration #9	2011-11-22	42.904 mi
Registration #10		11.777 es
		11,777 es
Registration #10		11.777 es 11.777 es
Registration #10 Registration #11		11,777 es 11,777 es 11,777 es
Registration #10 Registration #11 Registration #12		11,777 es 11,777 es 11,777 es 11,777 es
Registration #10 Registration #11 Registration #12 Registration #13		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11 777 46 11 777 46 11 777 46 11 777 46 11 777 46

More info >

CarCheck.co.uk page 10/11



Car features

-	•	•	•	-

The RENAULT factory car options list is only available in the premium report.

S0225 Air conditioning

S0295

S0482

S0501

S0566

S0567

S0569

View the complete RENAULT factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	****	
Video	see crash video	



Dimensions & weight

Width	1940 mm
Height	1417 mm
Length	3818 mm
Wheel base	2472 mm
Kerb weight	1040 kg

Additional information

Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number Carcheck.co.uk	D028502 page 11/11