





report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE VISIA
Colour	Red
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	128 Nm at 3.200 rpm
Engine capacity	1.386 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.7 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-08

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-22
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	20
Total items failed	3

MOT #13		2023-06-23 12:41
MOT test no	umber	425357325626
Result		✓ Passed
Next expiry	date	2024-06-22
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Nearside Front fog lamp not working	

MOT #12		2023-06-23 12:41
MOT test	number	179225733146
Result		× Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front fog lamp not working		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass wit	h rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/13



Pass with rectification

MJ10JNU report date: 2024-03-28

MOT test number

S29084569305

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #10
 2021-06-11 11:00

 MOT test number
 593505147160

 Result
 ✓ Passed

 MOT #9
 2021-06-09 10:55

 MOT test number
 266341530000

 Result
 X Failed

 Fail

 Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT test number

Result

Advice Front Brake pad(s) wearing thin brake discs are lipped (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



 MOT #6
 2018-09-21 13:02

 MOT test number
 445222566152

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2017-08-25 10:45

MOT test number 348329956173

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2016-08-23 10:17

MOT test number 790187469508

Result

Passed

MOT #3 2015-08-25 08:23

MOT test number 511321338258

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear tyre has fine aging cracks within its tread

Advice Offside Front Inner Tyre worn close to the legal limit and outer edges (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-08-26 10:10

MOT test number 609288834226

Result

Passed

Notice O/s/r tyre cracking slightly

CarCheck.co.uk page 5/13



MOT #1 2013-04-02 09:29

MOT test number 206702693029

Result ✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
have: Check it in the premium report and see an owner registrations. Download the full r	eport <u>nere</u> .

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK UK
Rinto circo	UK C
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-18
Last registration	2023-06-23
Complete history	See info



Registration #1	2010-05-18	28 mi
Registration #2	2013-04-02	26.291 mi
Registration #3	2014-08-26	31.895 mi
Registration #4	2015-08-25	36.423 mi
Registration #5	2016-08-23	39.877 mi
Registration #6	2017-08-25	43.425 mi
Registration #7	2018-09-21	47.554 mi
Registration #8	2019-08-21	50.747 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1691 mm
Height	1550 mm
Length	4083 mm
Wheel base	2600 mm
Kerb weight	1092 kg
Max. allowed weight	1546 kg

Additional information

Fuel tank capacity	46 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1