



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SPORT
Colour	Blue
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2022-02-18
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #14	2021-01-23 15:42
MOT test number	895447202597
Result	✓ Passed
Next expiry date	2022-02-18

MOT #13	2021-01-23 15:42
MOT test number	392437625933
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))

MOT #12	2020-01-23 10:28
MOT test number	251953421990
Result	✓ Passed

MOT #11	2019-02-14 11:56
MOT test number	910248127431
Result	✓ Passed

**MOT #10** 2019-02-14 09:51**MOT test number** 691223006472**Result** ✗ Failed**Fail** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**MOT #9** 2018-02-13 17:00**MOT test number** 407738380479**Result** ✓ Passed**Advice** Tyre worn close to the legal limit all four (4.1.E.1)**MOT #8** 2018-02-13 11:15**MOT test number** 532099037426**Result** ✗ Failed**Advice** Tyre worn close to the legal limit all four (4.1.E.1)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7** 2017-02-08 14:48**MOT test number** 712599790704**Result** ✓ Passed**MOT #6** 2016-02-15 14:29**MOT test number** 812151128452**Result** ✓ Passed

**MOT #5** 2015-02-16 17:13**MOT test number** 226407845088**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-02-19 17:33**MOT test number** 117600054477**Result** ✓ Passed**MOT #3** 2013-08-23 08:57**MOT test number** 325755233418**Result** ✓ Passed**MOT #2** 2013-01-29 16:25**MOT test number** 287619723007**Result** ✓ Passed**MOT #1** 2012-02-14 10:12**MOT test number** 349665242092**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-31
Last registration	2021-01-23
Complete history	See info



Registration #1	2009-03-31	9 mi
Registration #2	2012-02-14	39.541 mi
Registration #3	2013-01-29	49.624 mi
Registration #4	2013-08-23	52.587 mi
Registration #5	2014-02-19	52.695 mi
Registration #6	2015-02-16	70.473 mi
Registration #7	2016-02-15	76.569 mi
Registration #8	2017-02-08	81.952 mi
Registration #9	2018-02-08	81.952 mi
Registration #10	2018-02-08	81.952 mi
Registration #11	2018-02-08	81.952 mi
Registration #12	2018-02-08	81.952 mi
Registration #13	2018-02-08	81.952 mi
Registration #14	2018-02-08	81.952 mi
Registration #15	2018-02-08	81.952 mi
Registration #16	2018-02-08	81.952 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number

644153