



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-23
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-23
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	34
Total items failed	7

MOT #182023-01-24 12:37

MOT test number687169100134

Result✓ Passed

Next expiry date2024-01-23

Advice	Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Both handbrake mounting bracket corroded
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Rear Axle corroded and Suspension components corroded
Advice	Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #17**

2023-01-23 18:10

MOT test number

906698733030

Result**✗ Failed**

- Advice** Both handbrake mounting bracket corroded
- Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Rear Axle corroded and Suspension components corroded
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #16

2021-07-22 11:03

MOT test number

723304293108

Result**✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear sub frame slightly corroded
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Both front suspension arms slightly corroded

**MOT #15** 2021-07-20 09:18**MOT test number** 309006361848**Result** ✗ Failed

- Advice** Rear sub frame slightly corroded
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Both front suspension arms slightly corroded
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #14 2020-05-28 09:09**MOT test number** 752017766443**Result** ✓ Passed

- Advice** Rear brake pipes slightly corroded

MOT #13 2019-05-31 09:46**MOT test number** 538645381182**Result** ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12 2018-05-14 15:32**MOT test number** 448697940883**Result** ✓ Passed

- Advice** Vehicle showing signs of corrosion on sub frame's

**MOT #11** 2018-05-14 11:03**MOT test number** 147024871435**Result** ✗ Failed**Fail** Nearside front brake binding (3.7.B.1)**Advice** Vehicle showing signs of corrosion on sub frame's**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #10** 2017-05-23 13:57**MOT test number** 485323527216**Result** ✓ Passed**MOT #9** 2016-05-31 09:22**MOT test number** 157508541884**Result** ✓ Passed**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2015-06-02 09:33**MOT test number** 159563755132**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2014-04-17 11:01**MOT test number** 345577304103**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6** 2013-04-18 10:16**MOT test number** 678028903179**Result** ✓ Passed**Notice** Advise child seat base attached preventing full inspection of nearside rear seat belt**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2012-04-17 09:42**MOT test number** 245178702480**Result** ✓ Passed**MOT #4** 2011-03-25 13:05**MOT test number** 308814181075**Result** ✓ Passed**MOT #3** 2011-03-25 13:05**MOT test number** 185784081079**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2010-03-29 10:12**MOT test number** 570858280016**Result** ✓ Passed**MOT #1** 2009-04-14 12:14**MOT test number** 784314309186**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✗
MOT

Expired:
23 January 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	23 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GV06UFN
Plate since	2019-09-29
Current registration	GV06UFN
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-04-19
Last registration	2023-01-24
Complete history	See info



Registration #1	2006-04-19	25 mi
Registration #2	2009-04-14	22.453 mi
Registration #3	2010-03-29	28.675 mi
Registration #4	2011-03-25	36.166 mi
Registration #5	2012-04-17	43.853 mi
Registration #6	2013-04-18	48.145 mi
Registration #7	2014-04-17	51.496 mi
Registration #8	2015-06-02	55.607 mi
Registration #9	2016-05-31	59.172 mi
Registration #10	2017-05-23	62.024 mi
Registration #11	2018-05-23	65.000 mi
Registration #12	2019-05-23	68.000 mi
Registration #13	2020-05-23	71.000 mi
Registration #14	2021-05-23	74.000 mi
Registration #15	2022-05-23	77.000 mi
Registration #16	2023-05-23	80.000 mi
Registration #17	2024-05-23	83.000 mi
Registration #18	2025-05-23	86.000 mi
Registration #19	2026-05-23	89.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU778649