



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Red
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-01-18
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-02-13
<b>MOT pass rate</b>	69 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	33
<b>Total items failed</b>	10

**MOT #16** 2022-02-14 15:11**MOT test number** 108979210779**Result** ✓ Passed**Next expiry date** 2023-02-13

- Advice** Nearside sill corroded
- Advice** Both front upper strut mounts have slight movement
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside inner and outer sill badly corroded and weak
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2021-04-01 12:43**MOT test number** 733983564688**Result** ✓ Passed

- Advice** Sills and underbody corroded
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Chip in windsheild

**MOT #14**

2019-05-04 09:51

**MOT test number**

599401683799

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorating (5.3.4 (a) (i))

**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Nail in tread (NOT REPAIRABLE) (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorating (5.3.4 (a) (i))

**Advice** Exhaust corroded

**MOT #13**

2019-05-02 12:51

**MOT test number**

565975893706

**Result**

✗ Failed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorating (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Nail in tread (NOT REPAIRABLE) (5.2.3 (e))

**Advice** Exhaust corroded

**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush deteriorating (5.3.4 (a) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**MOT #12** 2018-04-26 08:26**MOT test number** 637111544402**Result** ✓ Passed**Advice** Front Registration plate damaged**Advice** Nearside Rear Tyre starting to wear close to legal limit**MOT #11** 2018-04-16 09:31**MOT test number** 243189129513**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Front Registration plate damaged**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Nearside Rear Tyre starting to wear close to legal limit**MOT #10** 2017-03-18 11:32**MOT test number** 399302287779**Result** ✓ Passed**MOT #9** 2017-03-18 11:32**MOT test number** 194306835339**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2016-03-09 11:09**MOT test number** 856007990736**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2015-03-13 15:22**MOT test number** 125562975060**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2015-03-13 12:00**MOT test number** 926532075078**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2014-02-26 12:50**MOT test number** 818097454040**Result** ✓ Passed**MOT #4** 2013-06-29 09:16**MOT test number** 796060283195**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2013-06-29 09:16**MOT test number** 909100783157**Result** ✓ Passed



MOT #2	2012-06-30 14:08
MOT test number	236012282428
Result	✓ Passed
<div>NoticeRear tyres perished outer side wall</div>	

MOT #1	2011-07-02 09:23
MOT test number	219683681141
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
7 November 2022

X

MOT

Expired:  
13 February 2023

Tax status	Expired at 7 November 2022
Days left	540 days too late
MOT expiry date	13 February 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>GL08VAY</b>
Plate since	2020-03-28
Current registration	<b>GL08VAY</b>
Plate since	2020-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-06-26
Last registration	2022-02-14
Complete history	<a href="#">See info</a>



Registration #1	2008-06-26	25 mi
Registration #2	2011-07-02	19.925 mi
Registration #3	2012-06-30	23.385 mi
Registration #4	2013-06-29	32.432 mi
Registration #5	2014-02-26	33.752 mi
Registration #6	2015-03-13	45.610 mi
Registration #7	2015-03-13	45.610 mi
Registration #8	2016-03-09	52.567 mi
Registration #9	2017-03-18	64.203 mi
Registration #10	2018-03-27	75.377 mi
Registration #11	2019-03-27	86.551 mi
Registration #12	2020-03-27	97.725 mi
Registration #13	2021-03-27	108.899 mi
Registration #14	2022-03-27	120.073 mi
Registration #15	2023-03-27	131.247 mi
Registration #16	2024-03-27	142.421 mi
Registration #17	2025-03-27	153.595 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 062931