



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	White
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-07-21
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-18
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	27
Total items failed	9

MOT #18	2023-06-14 08:55
MOT test number	747831954110
Result	✓ Passed
Next expiry date	2024-06-18

MOT #17	2022-06-09 15:25
MOT test number	367763878636
Result	✓ Passed

MOT #16	2022-06-09 07:53
MOT test number	429933029285
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing 175/65/15T (5.2.3 (d) (ii))

MOT #15	2021-06-19 10:54
MOT test number	942240356180
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-06-19 10:54**MOT test number** 185618086508**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-05-22 15:44**MOT test number** 621823732192**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2020-05-22 08:50**MOT test number** 138743479408**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**MOT #11** 2019-02-02 11:24**MOT test number** 433973314135**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Items removed from driver's view prior to test

**MOT #10** 2018-02-02 10:06**MOT test number** 900520809485**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Oil leak
- Advice** Exhaust emits blue smoke during acceleration (7.3.A.2c)

MOT #9 2018-02-02 10:06**MOT test number** 755460752348**Result** ✗ Failed

- Advice** Oil leak
- Advice** Exhaust emits blue smoke during acceleration (7.3.A.2c)
- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)
- Advice** Items removed from driver's view prior to test

MOT #8 2017-01-30 10:10**MOT test number** 674487302773**Result** ✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake pad(s) wearing thin both (3.5.1g)
- Advice** Items removed from driver's view prior to test

**MOT #7** 2017-01-30 10:10**MOT test number** 474343688395**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Brake pad(s) wearing thin both (3.5.1g)**Advice** Items removed from driver's view prior to test**Pass with rectification** Front Headlamp aim too low both (1.8)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2016-01-26 11:49**MOT test number** 320856745444**Result** ✓ Passed**MOT #5** 2015-01-31 14:13**MOT test number** 365151535048**Result** ✓ Passed**MOT #4** 2014-03-03 09:22**MOT test number** 166562064008**Result** ✓ Passed**Notice** Rear bumper protruding but no sharp edges**Notice** Wipers smearing slightly**MOT #3** 2013-02-25 15:08**MOT test number** 757386453024**Result** ✓ Passed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** Nearside sill section dented



MOT #2 2013-02-25 14:49

MOT test number 495066253048

Result ✗ Failed

Notice Nearside sill section dented

Advice Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Fail Nearside Rear Body insecure and dangerous to other road users (6.1.B.1b)

MOT #1 2012-03-06 09:23

MOT test number 206776762047

Result ✓ Passed

Notice Nearside door mirror insecure

Notice Nearside sill damaged



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
18 June 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	18 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YK09XJD
Plate since	2024-03-29
Current registration	YK09XJD
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-09
Last registration	2023-06-14
Complete history	See info



Registration #1	2009-03-09	14 mi
Registration #2	2012-03-06	15.634 mi
Registration #3	2013-02-25	21.218 mi
Registration #4	2013-02-25	21.218 mi
Registration #5	2014-03-03	27.156 mi
Registration #6	2015-01-31	30.794 mi
Registration #7	2016-01-26	33.925 mi
Registration #8	2017-01-30	39.174 mi
Registration #9	2017-01-30	39.174 mi
Registration #10	2018-02-02	44.761 mi
Registration #11	2019-03-09	50.349 mi
Registration #12	2020-03-06	56.983 mi
Registration #13	2021-02-25	63.617 mi
Registration #14	2022-03-03	70.251 mi
Registration #15	2023-03-03	76.885 mi
Registration #16	2024-03-03	83.519 mi
Registration #17	2025-03-03	90.153 mi
Registration #18	2026-03-03	96.787 mi
Registration #19	2027-03-03	103.421 mi
Registration #20	2028-03-03	110.055 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1KR0827053