





General information

Make	HYUNDAI
Model	140 CRDI STYLE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С







try 1			
ate	2021-11-3	10	
ictures	6		
isting price	View repo	ort	
AutoTrader Highly Rated FOR OUR CUSTOMER SERVICE 2021	AutoTrader Highly Rated FOR OUR CUSTOMER SERVICE 2020	<image/> <section-header><section-header><text><text><section-header><text></text></section-header></text></text></section-header></section-header>	FINANCE YOUR NEXT CAR MOCIONO FIST RESPONSE MOCIONO M

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #9		2023-07-17 12:06
MOT test	number	499841394850
Result		✓ Passed
Next expi	ry date	2024-07-20
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 205/60R16	(5.2.3 (e))
Advice (d) (ii))	Nearside Rear Tyre slightly damaged/cracking or perishing 205/60R16.	Also has nail in tyre. (5.2.3
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in ex	cessive movement (5.3.4
Advice	Offside Front Tyre worn close to legal limit/worn on edge 205/60R16 (5	.2.3 (e))

MOT #8	2022-07-20 09:11
MOT test	number 459682902850
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge outer edge & perished (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge 205/60/16 (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))





MOT #7	2022-07-19 10:58	
MOT test number	318278391134	
Result	🗙 Failed	
Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge outer edge & perished (5.2.3 (e))		
Fail Rear Registration plate inscription illegible (0.1 (b))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge	205/60/16 (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge outer edge (5	.2.3 (e))	

МОТ #6	2021-07-02 08:34
MOT test number	459506664564
Result	✓ Passed

MOT #5	2020-07-21 08:49
MOT test number	186389049857
Result	✓ Passed

MOT #4		2019-06-27 07:50
MOT test	number	963247517954
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Wheel bearing has slight play $(5.1.3 (a) (i))$	

MOT #3	2018-06-29 08:53
MOT test number	533714673249
Result	✓ Passed
Advice Nearside Rear Nail in tyre	





MOT #2		2017-07-21 07:58
MOT test number		706759914646
Result		✓ Passed
MOT #1		2017-07-21 07:58
MOT test number		827417659324
Result		🗙 Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	





Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 20 July 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	20 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et a
Date	*
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

and the second se	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-01-31
Last registration	2023-07-17
Complete history	See info



Registration #1	2014-01-31	26 mi
Registration #2	2017-07-21	40.534 mi
Registration #3	2017-07-21	40.534 mi
Registration #4	2018-06-29	47.622 mi
Registration #5	2019-06-27	56.808 mi
Registration #6	2020-07-21	63.762 mi
Registration #7		11.777 est
Registration #8		11.227 est
Registration #9		11.777 est
Registration #10		11.317 est
Registration #11		11.317 est





Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	D4FDEU412572