




report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	32.1 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M





Internet history

Entry 2

Date	2023-08-02
Pictures	34
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-16
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-17
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	25
Total items failed	9

MOT #19	2023-08-18 13:55
MOT test number	305530452384
Result	✓ Passed
Next expiry date	2024-08-17

MOT #18	2023-08-16 15:31
MOT test number	720916636804
Result	✗ Failed
Fail	Hazard warning switch inoperative (4.4.2 (a) (ii))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #17	2022-10-13 08:25
MOT test number	122106262860
Result	✓ Passed
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #16** 2022-10-12 15:32**MOT test number** 535927646850**Result** ✗ Failed**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15** 2021-09-15 11:12**MOT test number** 195429410201**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2021-09-15 10:07**MOT test number** 372022891945**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Driver's airbag obviously inoperative (7.1.5 (c))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2020-10-12 12:34

MOT test number

672085236942

Result

✓ Passed

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12**

2020-10-12 12:34

MOT test number

683506972563

Result

✗ Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11**

2019-04-05 12:25

MOT test number

780956388910

Result

✓ Passed

MOT #10

2018-03-26 10:07

MOT test number

932163151931

Result

✓ Passed

**MOT #9** 2017-04-11 13:07**MOT test number** 657933041255**Result** ✓ Passed**MOT #8** 2017-03-30 07:08**MOT test number** 383099786227**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #7** 2016-03-24 14:45**MOT test number** 465259628494**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-03-30 11:07**MOT test number** 268879085076**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-08-09 10:39**MOT test number** 336971024292**Result** ✓ Passed

**MOT #4** 2013-08-10 11:57**MOT test number** 619972723286**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-05-05 10:39**MOT test number** 516826422118**Result** ✓ Passed**MOT #2** 2011-05-05 12:28**MOT test number** 907135021163**Result** ✓ Passed**MOT #1** 2010-03-18 16:05**MOT test number** 853257870010**Result** ✓ Passed**Notice** Front tyres cracking slightly along tread**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Rear tyres getting low and also cracked



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-29
Last registration	2023-08-18
Complete history	See info



Registration #1	2007-03-29	21 mi
Registration #2	2010-03-18	11.342 mi
Registration #3	2011-05-05	15.646 mi
Registration #4	2012-05-05	21.532 mi
Registration #5	2013-08-10	26.692 mi
Registration #6	2014-08-09	29.667 mi
Registration #7	2015-03-30	31.734 mi
Registration #8	2016-03-24	33.915 mi
Registration #9	2017-03-30	36.680 mi
Registration #10	2017-04-11	36.690 mi
Registration #11	2018-03-26	38.314 mi
Registration #12	2019-03-29	39.337 mi
Registration #13	2020-03-29	40.360 mi
Registration #14	2021-03-29	41.383 mi
Registration #15	2022-03-29	42.406 mi
Registration #16	2023-03-29	43.429 mi
Registration #17	2023-08-18	44.452 mi
Registration #18	2023-08-18	44.452 mi
Registration #19	2023-08-18	44.452 mi
Registration #20	2023-08-18	44.452 mi
Registration #21	2023-08-18	44.452 mi
Registration #22	2023-08-18	44.452 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1542 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	577793