



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Black
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-02-13
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-12
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-02
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	33
Total items failed	5

MOT #18	2024-02-03 09:32
MOT test number	264774325297
Result	✓ Passed
Next expiry date	2025-02-02

MOT #17	2023-01-26 11:15
MOT test number	719280835003
Result	✓ Passed
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2023-01-25 13:38

MOT test number

698347590977

Result

✗ Failed

Fail Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #15**

2022-02-01 10:12

MOT test number

470342612649

Result

✓ Passed

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #14**

2020-11-23 09:31

MOT test number

817892846575

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Park brake requires adjustment**MOT #13**

2019-11-08 08:46

MOT test number

162972142406

Result

✓ Passed

**MOT #12**

2019-10-07 12:13

MOT test number

973982946357

Result

✗ Failed

Advice Parking brake lever operation high**Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11**

2018-10-11 08:27

MOT test number

863977065050

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre tread at 2mm (5.2.3 (e))**Advice** Front Subframe mounting prescribed area damaged but not considered excessive sub-frame corroded not excessive also suspension components corroded but strong (5.3.6 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge tyre tread at 3mm (5.2.3 (e))**Advice** Rear Subframe mounting prescribed area damaged but not considered excessive some corrosion in prescribed area not excessive , also suspension components corroded but strong (5.3.6 (a) (i))**MOT #10**

2017-10-13 08:17

MOT test number

501455435505

Result

✓ Passed

Advice Nearside and offside headlamp glasses starting to deteriorate**MOT #9**

2016-10-10 12:31

MOT test number

411580834981

Result

✓ Passed

Advice Surface corrosion on front lower suspension arms**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #8** 2015-05-30 11:29**MOT test number** 896810255167**Result** ✓ Passed**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**Notice** Rear tyres feathered**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)**MOT #7** 2014-06-07 12:14**MOT test number** 385108154137**Result** ✓ Passed**MOT #6** 2013-06-01 13:01**MOT test number** 968602253144**Result** ✓ Passed**MOT #5** 2013-06-01 13:01**MOT test number** 439702153183**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2012-06-02 09:20**MOT test number** 975724052144**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.D.2c)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-05-31 14:35**MOT test number** 598021951129**Result** ✓ Passed**MOT #2** 2010-09-15 12:53**MOT test number** 734628750264**Result** ✓ Passed**MOT #1** 2009-09-16 11:31**MOT test number** 494799659288**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-11
Last registration	2024-02-03
Complete history	See info



Registration #1	2006-10-11	28 mi
Registration #2	2009-09-16	22.824 mi
Registration #3	2010-09-15	28.104 mi
Registration #4	2011-05-31	30.780 mi
Registration #5	2012-06-02	37.217 mi
Registration #6	2013-06-01	46.196 mi
Registration #7	2014-06-07	52.865 mi
Registration #8	2015-05-30	59.170 mi
Registration #9	2016-10-10	65.331 mi
Registration #10	2017-10-13	69.686 mi
Registration #11	2018-05-29	75.331 mi
Registration #12	2019-05-29	81.331 mi
Registration #13	2020-05-29	87.331 mi
Registration #14	2021-05-29	93.331 mi
Registration #15	2022-05-29	99.331 mi
Registration #16	2023-05-29	105.331 mi
Registration #17	2024-02-03	111.331 mi
Registration #18	2024-02-03	117.331 mi
Registration #19	2024-02-03	123.331 mi
Registration #20	2024-02-03	129.331 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU778649