



report date: 2024-03-29

General information

Make	LAND ROVER
Model	RANGE ROVER SDV8 AUTOBIOGRAPHY
Colour	Black
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	6.6 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	334 BHP
Max. torque	739 Nm at 2.250 rpm
Cylinders	8
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	37.2 mpg
Consumption combined	33.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-18
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #4</b>	2022-06-30 15:35
<b>MOT test number</b>	811650708639
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-06-29

<b>MOT #3</b>	2022-06-30 11:26
<b>MOT test number</b>	991841036300
<b>Result</b>	✗ Failed

**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #2</b>	2022-03-09 10:22
<b>MOT test number</b>	179253861228
<b>Result</b>	✓ Passed

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**Advice** Inner Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))

**Advice** Rear Inner Brake pad(s) wearing thin 1.7mm (1.1.13 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Nail in tyre not repairable

**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

<b>MOT #1</b>	2021-02-17 11:17
<b>MOT test number</b>	805167315352
<b>Result</b>	✓ Passed



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-03-02
Last registration	2022-06-30
Complete history	<a href="#">See info</a>



Registration #1	2018-03-02	21 mi
Registration #2	2021-02-17	54.419 mi
Registration #3	2022-03-09	72.439 mi
Registration #4	2022-06-30	75.277 mi
Registration #5	2022-06-30	75.277 mi
Registration #6	2022-06-30	75.277 mi

More info >





Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2220 mm
Height	1868 mm
Length	5200 mm
Wheel base	3120 mm

Additional information

Fuel tank capacity	86 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0073543448DT