



report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO MULTIAIR GP
Colour	Red
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1	
Date	2022-03-29
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-11
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	51
Total items failed	20

MOT #18	2023-05-12 13:59
MOT test number	820753123562
Result	✓ Passed
Next expiry date	2024-05-11
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Front Exhaust noisy (8.1.1 (a))

MOT #17	2022-04-07 14:41
MOT test number	203808149919
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2022-04-07 13:52
MOT test number	393537413521
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #15**

2022-03-16 10:54

MOT test number

393278408923

Result

✗ Failed

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Rear of vehicle full of rubbish**Fail** Offside Front Coil spring mounting insecure to the extent that relative movement is visible top spring mount (5.3.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Items removed from driver's view prior to test**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Tyre has ply or cords exposed 195/55R16 (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Exhaust emissions likely to be affected by an exhaust leak front pipe excessive leak [flexi] (8.2.2.1 (b))**MOT #14**

2021-02-27 14:33

MOT test number

228255156570

Result

✓ Passed

Advice Nearside Front day time running lamp not working.**Advice** Exhaust has a minor leak of exhaust gases front flexy. (6.1.2 (a))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Chip on windscreen**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #13**

2021-02-27 12:35

MOT test number

663644382756

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases front flexy. (6.1.2 (a))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Chip on windscreen
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Fuel cap/sealing device missing (6.1.3 (b) (i))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Nearside Front day time running lamp not working.
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12

2020-03-06 13:57

MOT test number

495337757947

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front tyre outer edge worn and perishing
- Advice** Nearside Rear tyre outer edge worn
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust backbox rusty
- Advice** Offside Front suspension top mount noisy

**MOT #11**

2020-03-06 09:23

MOT test number

712762684654

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear tyre outer edge worn
- Advice** Exhaust backbox rusty
- Advice** Offside Front suspension top mount noisy
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Offside Front tyre outer edge worn and perishing
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2019-03-20 16:01

MOT test number

888102636257

Result**✓ Passed**

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front tyre worn low on edges of tread
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #9**

2019-03-20 16:01

MOT test number

277641328381

Result**✗ Failed****Pass with rectification** Nearside Windscreen washer not working (3.5 (a))**Advice** Nearside Front tyre worn low on edges of tread**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Offside Windscreen washer not working (3.5 (a))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #8**

2018-03-19 09:12

MOT test number

809970534519

Result**✓ Passed****Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #7**

2018-03-19 09:12

MOT test number

326485111306

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #6** 2017-03-20 10:03**MOT test number** 332472101490**Result** ✓ Passed**Advice** Rear exhaust corroded**MOT #5** 2016-03-16 08:40**MOT test number** 230063277848**Result** ✓ Passed**Advice** Engine oil leak**MOT #4** 2015-03-16 09:25**MOT test number** 366095075003**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-10 11:12**MOT test number** 345209164055**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-03-12 15:40**MOT test number** 878251673098**Result** ✓ Passed**Notice** Nearside front fog lamp insecure



MOT #1	2013-03-11 17:38
MOT test number	895720973039
Result	✗ Failed
Fail	Nearside Headlamp insecure (1.7.3)
Notice	Nearside front fog lamp insecure



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 May 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-13
Last registration	2023-05-12
Complete history	See info



Registration #1	2010-03-13	20 mi
Registration #2	2013-03-11	28.654 mi
Registration #3	2013-03-12	28.660 mi
Registration #4	2014-03-10	43.987 mi
Registration #5	2015-03-16	49.720 mi
Registration #6	2016-03-16	61.098 mi
Registration #7	2017-03-20	73.244 mi
Registration #8	2018-03-19	80.682 mi
Registration #9	2018-03-19	80.682 mi
Registration #10	2019-03-20	85.147 mi
Registration #11	2019-03-20	85.147 mi
Registration #12	2019-03-20	85.147 mi
Registration #13	2019-03-20	85.147 mi
Registration #14	2019-03-20	85.147 mi
Registration #15	2019-03-20	85.147 mi
Registration #16	2019-03-20	85.147 mi
Registration #17	2019-03-20	85.147 mi
Registration #18	2019-03-20	85.147 mi
Registration #19	2019-03-20	85.147 mi
Registration #20	2019-03-20	85.147 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

1482256