





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | IONIQ PREMIUM SE |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 115 mph |
| 0 - 60 mph | 10.8 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 104 BHP |
|-------------------------|---------------------|
| Max. torque | 265 Nm at 4.000 rpm |
| Engine capacity | 1.580 сс |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 78.5 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 78.5 mpg |
| CO2 emission | 84 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/11



SC68ETT

report date: 2024-03-28

Internet history

Entry 1

| Date | 2022-04-11 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-02-15 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 12 |
| Total items failed | 2 |

| MOT #4 | | 2024-02-10 12:37 |
|---------------------------|---|--------------------|
| MOT test | number | 923754114244 |
| Result | | ✓ Passed |
| Next expi | iry date | 2025-02-15 |
| Advice (f)) | Offside Rear Service brake binding but not excessively wheel brake binding (str | ong advise) (1.2.1 |
| Advice | Offside Rear Brake pad(s) wearing thin brake pads seem to be getting low (1.1. | 13 (a) (ii)) |
| Advice | Offside Rear tyre has got a split in tyre tread quite deep (strong advise) 195/65 | /15 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge tyre on 3mm 195/65 | /15 (5.2.3 (e)) |
| Advice (1.1.14 (a) | Brake disc worn, pitted or scored, but not seriously weakened both rear brake d | liscs corroding |
| Advice | Handbrake travel slightly long | |

CarCheck.co.uk page 3/11



SC68ETT

report date: 2024-03-28

MOT #3 2024-02-10 11:32 **MOT** test number 452517527921 Result × Failed Fail Fuel hose insecure fuel hose to fuel tank clamp insecure (6.1.3 (a) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre on 3mm 195/65/15 (5.2.3 (e)) **Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear brake discs corroding (1.1.14 (a) (ii)) **Advice** Offside Rear tyre has got a split in tyre tread quite deep (strong advise) 195/65/15 Pass with rectification Headlamp aim too far to the right both front (4.1.2 (a)) **Advice** Offside Rear Service brake binding but not excessively wheel brake binding (strong advise) (1.2.1 (f)) Offside Rear Brake pad(s) wearing thin brake pads seem to be getting low (1.1.13 (a) (ii)) **Advice Advice** Handbrake travel slightly long

| MOT #2 | 2023-02-11 12:34 |
|-----------------|------------------|
| MOT test number | 263822264397 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2022-01-24 11:04 |
| MOT test number | 900492451024 |
| Result | ./ Passed |

CarCheck.co.uk page 4/11



10port date

Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 338 |
| MOT expiry date | 15 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

SC68ETT

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-02-16 |
| Last registration | 2024-02-10 |
| Complete history | See info |



| Registration #1 | 2019-02-16 | 14 mi |
|-----------------|------------|-----------|
| Registration #2 | 2022-01-24 | 10.751 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 0.77 |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 80% |
| Pedestrian | 70% |
| Safety systems | 82% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 2045 mm |
|---------------------|---------|
| Height | 1450 mm |
| Length | 4470 mm |
| Wheel base | 2700 mm |
| Max. allowed weight | 1870 kg |

Additional information

| Fuel tank capacity | 45 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |

Engine number

G4LEJU159744