



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	Black
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-31
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-15
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	27
Total items failed	3

MOT #14	2023-10-14 13:54
MOT test number	622413133382
Result	✓ Passed
Next expiry date	2024-10-15
Advice	Rear surface corrosion on suspension components

MOT #13	2022-10-13 12:54
MOT test number	697602941987
Result	✓ Passed
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #12**

2022-10-13 12:54

**MOT test number**

116681570375

**Result**

✗ Failed

**Pass with rectification**

Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice**

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

**Advice**

Oil leak, but not excessive Engine (8.4.1 (a) (i))

**Advice**

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

**MOT #11**

2021-10-16 07:56

**MOT test number**

819988995727

**Result**

✓ Passed

**Advice**

Coil spring corroded Both rear springs corroded but don't appear to be broken (5.3.1 (b) (i))

**Advice**

Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice**

Brake disc worn, pitted or scored, but not seriously weakened Rear face of front disks lightly pitted and corroded (1.1.14 (a) (ii))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge worn below 1.6mm on inner edge (5.2.3 (e))

**Minor**

Stop lamp(s) with a multiple light source up to 1/2 not functioning centre stop light has a couple of bulbs not working (4.3.1 (a) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm bushes splitting (5.3.4 (a) (i))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge worn to 2mm and below on both edges (5.2.3 (e))

**MOT #10**

2020-10-16 13:09

**MOT test number**

703083103692

**Result**

✓ Passed

**MOT #9** 2019-04-13 07:31**MOT test number** 904586251925**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #8** 2018-04-14 13:00**MOT test number** 919874982740**Result** ✓ Passed**Advice** Offside Rear tyre out of shape/wearing inner edge**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2018-04-14 11:41**MOT test number** 191480467457**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear tyre out of shape/wearing inner edge**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2017-03-30 13:24**MOT test number** 660918985592**Result** ✓ Passed**Advice** Offside Front tyre wearing on inner edge**MOT #5** 2016-03-22 12:33**MOT test number** 676560579519**Result** ✓ Passed



MOT #4	2015-06-09 15:04
MOT test number	767670865158
Result	✓ Passed
MOT #3	2014-06-10 11:48
MOT test number	966161264164
Result	✓ Passed
MOT #2	2013-06-27 15:38
MOT test number	526078573160
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2012-07-04 15:05
MOT test number	897986282184
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
15 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	15 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EJ09SZF
Plate since	2019-03-28
Current registration	EJ09SZF
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-07-24
Last registration	2023-10-14
Complete history	<a href="#">See info</a>



Registration #1	2009-07-24	27 mi
Registration #2	2012-07-04	31.693 mi
Registration #3	2013-06-27	42.237 mi
Registration #4	2014-06-10	51.740 mi
Registration #5	2015-06-09	61.431 mi
Registration #6	2016-03-22	68.740 mi
Registration #7	2017-03-30	74.906 mi
Registration #8	2018-04-14	78.385 mi
Registration #9	2019-05-20	81.277 mi
Registration #10	2020-05-20	84.277 mi
Registration #11	2021-05-20	87.277 mi
Registration #12	2022-05-20	90.277 mi
Registration #13	2023-05-20	93.277 mi
Registration #14	2024-05-20	96.277 mi
Registration #15	2025-05-20	99.277 mi
Registration #16	2026-05-20	102.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	9K80515