





report date: 2024-03-28

General information

Make	BMW
Model	435 435D XDRIVE M SPORT
Colour	Black
Year of manufacture	2017
Top speed	155 mph
0 - 60 mph	4.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date 2023-07-23

Pictures 42

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-10-05	
------	------------	--

Pictures 46

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-04
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-08-02
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #6	2023-08-03 07:42
MOT test number	932765452490
Result	✓ Passed
Next expiry date	2024-08-02

MOT #5		2023-01-28 11:25
MOT test	number	667744768878
Result		✓ Passed
Advice	Engine covers and under trays fitted to the vehicle	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Tested in a dirty condition	

MOT #4		2022-02-07 13:24
MOT test	number	729254511466
Result		✓ Passed
Advice Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Undertrays fitted

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2021-03-19 09:01 **MOT** test number 616504122012 Result **X** Failed Undertrays fitted **Advice Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2020-03-15 13:39
MOT test number	933908101671
Result	✓ Passed
Advice Tyre worn close to legal limit/worn on edge nearside rear (5.2.3 (e))	

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



BG17NTY report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have the Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.			
Plate changes See in this check if this BMW had different number plates.			ve?
Plate changes See in this check if this BMW had different number plates.			
Plate changes See in this check if this BMW had different number plates.			
Plate changes See in this check if this BMW had different number plates.			
Plate changes See in this check if this BMW had different number plates.			
Plate changes See in this check if this BMW had different number plates.	PROPERTY.		
Plate changes See in this check if this BMW had different number plates.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Plate changes See in this check if this BMW had different number plates.	************		
See in this check if this BMW had different number plates.		More info	>
器 UK	Plate changes		
NE UK	See in this check if this BMW had different number plates.		
NE UK	Number of plates		
Platte since	Current registration	NK NK	
Platte since	Plate since		
More info >	Current registration	UK UK	
More info >	Plate since		
		More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-17
Last registration	2023-08-03
Complete history	See info



Registration #1	2017-03-17	15 mi
Registration #2	2020-03-15	26.312 mi
Registration #3	2021-03-19	34.315 mi
Registration #4	2021-03-19	34.324 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		T1.777 es

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1825 mm
Height	1392 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1625 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 11/1

Number of axles 2

Engine number 74149799