



SH60FPP

report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V MULTIJET SX
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN

**MOT history**

MOT #13	2020-11-02 16:14
MOT test number	893177043699
Result	✓ Passed
Next expiry date	2021-11-13

MOT #12	2020-11-02 16:14
MOT test number	279536183361
Result	✗ Failed
Pass with rectification Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	

MOT #11	2019-10-24 13:42
MOT test number	959152082852
Result	✓ Passed

MOT #10	2019-10-24 13:42
MOT test number	750457345666
Result	✗ Failed
Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #9	2018-10-15 12:24
MOT test number	147453551502
Result	✓ Passed

MOT #8	2017-10-26 13:48
MOT test number	339552934632
Result	✓ Passed

MOT #7	2016-10-25 12:10
MOT test number	131040252703
Result	✓ Passed

**MOT #6** 2016-10-19 13:21**MOT test number** 821107659515**Result** ✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Upper Shock absorber has an excessively worn shock absorber pivot (2.7.4)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Front Upper Shock absorber has a slightly worn shock absorber pivot (2.7.4)

MOT #5 2015-10-19 12:57**MOT test number** 384932497025**Result** ✓ Passed

- Advice** Nearside Front Upper Shock absorber has a slightly worn shock absorber pivot (2.7.4)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Upper Shock absorber has a slightly worn shock absorber pivot (2.7.4)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-11-14 18:23**MOT test number** 688948414329**Result** ✓ Passed**MOT #3** 2014-11-05 18:44**MOT test number** 825509204397**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)



MOT #2	2013-10-17 11:31
MOT test number	319790993442
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-10-17 11:31
MOT test number	588690393272
Result	✗ Failed
Pass with rectification	Offside Front Power steering fluid level below minimum (2.3.1)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Pass with rectification	Nearside Outer Rear Registration plate lamp not working (1.1.C.1d)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-12-31
Last registration	2020-11-02
Complete history	See info



Registration #1	2010-12-31	13 mi
Registration #2	2013-10-17	32.684 mi
Registration #3	2014-11-05	25.306 mi
Registration #4	2014-11-14	37.673 mi
Registration #5	2015-10-19	42.678 mi
Registration #6	2016-10-19	47.992 mi
Registration #7	2016-10-25	48.080 mi
Registration #8	2019-05-29	55.277 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3632544