





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

		1
ᆮ	HLIV	-

End y 1	
Date	2021-06-16
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-08-07
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #8	2023-08-08 16:26
MOT test number	318423988257
Result	✓ Passed
Next expiry date	2024-08-07

MOT #7	2022-08-04 08:41
MOT test number	317868817760
Result	√ Passed

MOT #6	2021-08-07 12:11
MOT test number	205706418654
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	

MOT #5	2020-07-17 10:28
MOT test number	517361920736
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2019-06-19 12:09

MOT test number 319268258143

MOT #3 2018-06-18 10:16

MOT test number 206125908430

Result

Passed

Minor Nearside Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2018-06-18 10:16

MOT test number 949787758178

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))

MOT #1 2017-06-02 08:51

MOT test number 147581261935

Result
✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category

Damage 2

Type

Date

Dailiage 2

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-06-30
Last registration	2023-08-08
Complete history	See info



Registration #1	2014-06-30	6 mi
Registration #2	2017-06-02	54.460 mi
Registration #3	2018-06-18	77.168 mi
Registration #4	2018-06-18	77.168 mi
Registration #5	2019-06-19	95.552 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.00 m
•		11.77 m
Registration #7		11.77 es 11.77 es 11.77 es

More info >

CarCheck.co.uk page 10/11



GM14CDY report date: 2024-03-28

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 11/11