



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TAKARA
Colour	Blue
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	146 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.5 mpg
CO2 emission	194 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-09-19
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-04
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	40
Total items failed	15

MOT #17	2024-03-05 18:03
MOT test number	444012464553
Result	✓ Passed
Next expiry date	2025-03-04
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16**

2024-02-19 12:27

MOT test number

930059355302

Result

✗ Failed

Advice Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Lower Fog lamp/inoperative**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15**

2023-02-25 13:29

MOT test number

621752094547

Result

✓ Passed

Advice N/S/F tyre on 3.7mm tread**Advice** O/S/F tyre on 4mm tread**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #14**

2022-02-25 15:06

MOT test number

286721159267

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #13	2022-02-25 15:06
MOT test number	326661670247
Result	✗ Failed
Pass with rectification	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2021-02-11 16:48
MOT test number	928682237384
Result	✓ Passed
Advice	Nearside Front Lower spot light not working
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2021-02-11 12:09
MOT test number	778309250027
Result	✗ Failed
Advice	Nearside Front Lower spot light not working
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))

MOT #10	2020-01-23 12:29
MOT test number	830934112081
Result	✓ Passed
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #9**

2019-02-14 17:53

MOT test number

521619031987

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2018-03-13 16:19

MOT test number

937997797090

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear tyre starting to wear on inner edge**Advice** Offside Rear Tyre worn close to the legal limit and bald on inner edge (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7**

2018-03-05 10:29

MOT test number

827764292683

Result**✗ Failed**

Fail Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear support bush (2.4.G.2)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit and bald on inner edge (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement rear support bush (2.4.G.2)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear tyre starting to wear on inner edge

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #6

2017-03-13 10:41

MOT test number

980531197968

Result**✓ Passed**

Advice Covers & shields fitted not allowing full inspection

MOT #5

2017-03-13 10:41

MOT test number

430991236409

Result**✗ Failed**

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Advice Covers & shields fitted not allowing full inspection

**MOT #4** 2016-03-11 12:17**MOT test number** 563358372859**Result** ✓ Passed**MOT #3** 2015-03-21 08:50**MOT test number** 158750185055**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-07-31 10:25**MOT test number** 969772213235**Result** ✓ Passed**Notice** NSR tyre worn on edges**Notice** OSR tyre worn on edges**MOT #1** 2013-03-21 15:48**MOT test number** 626670083088**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** All four tyres worn on edges



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 March 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-19
Last registration	2024-03-05
Complete history	See info



Registration #1	2010-04-19	17 mi
Registration #2	2013-03-21	30.907 mi
Registration #3	2013-07-31	33.813 mi
Registration #4	2015-03-21	50.190 mi
Registration #5	2016-03-11	59.680 mi
Registration #6	2017-03-13	71.523 mi
Registration #7	2017-03-13	71.523 mi
Registration #8	2018-03-05	87.268 mi
Registration #9	2018-03-13	87.541 mi
Registration #10	2019-02-14	93.541 mi
Registration #11	2019-03-20	95.557 mi
Registration #12	2019-03-20	95.557 mi
Registration #13	2019-03-20	95.557 mi
Registration #14	2019-03-20	95.557 mi
Registration #15	2019-03-20	95.557 mi
Registration #16	2019-03-20	95.557 mi
Registration #17	2019-03-20	95.557 mi
Registration #18	2019-03-20	95.557 mi
Registration #19	2019-03-20	95.557 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1475 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	LF 10962950