



HYUNDAI



IRZ4535


report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 STYLE
Colour	Grey
Year of manufacture	2014
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	140 g/km
CO2 label	E







Internet history

Entry 2

Date	2021-09-24
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-24
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-10-31
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	23
Total items failed	17

MOT #13	2023-11-01 14:04
MOT test number	881205409580
Result	✓ Passed
Next expiry date	2024-10-31
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #12

2023-10-30 13:36

MOT test number

920701884133

Result		✗ Failed
Fail	Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail	Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

**MOT #11**

2023-10-25 15:47

MOT test number

986439858918

Result**✗ Failed**

- Fail** Offside Front Wheel bearing play so excessive that directional control is impaired (5.1.3 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Parking brake has little reserve travel
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #10

2022-09-28 11:13

MOT test number

140064749762

Result**✓ Passed****MOT #9**

2022-09-27 16:33

MOT test number

352605064454

Result**✗ Failed**

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #8** 2021-09-29 14:04**MOT test number** 666798236663**Result** ✓ Passed**MOT #7** 2020-10-31 09:56**MOT test number** 230335916415**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing in-between tyre tread blocks (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing in-between tyre tread blocks (5.2.3 (d) (ii))**MOT #6** 2020-10-31 08:39**MOT test number** 460882214731**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing in-between tyre tread blocks (5.2.3 (d) (ii))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing in-between tyre tread blocks (5.2.3 (d) (ii))**MOT #5** 2019-11-08 17:53**MOT test number** 825442410554**Result** ✓ Passed**MOT #4** 2019-11-08 17:53**MOT test number** 371985601578**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #3** 2018-11-23 13:54**MOT test number** 585261871672**Result** ✓ Passed

**MOT #2** 2018-11-22 10:35**MOT test number** 215890619207**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-11-21 10:23**MOT test number** 602285433593**Result** ✓ Passed**Advice** Exhaust corroded



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 October 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-09-30
Last registration	2023-11-01
Complete history	See info



Registration #1	2014-09-30	22 mi
Registration #2	2017-11-21	36.333 mi
Registration #3	2018-11-22	45.022 mi
Registration #4	2018-11-23	45.023 mi
Registration #5	2019-11-08	52.882 mi
Registration #6	2019-11-08	52.882 mi
Registration #7	2020-10-31	58.396 mi
Registration #8	2020-10-31	58.396 mi
Registration #9	2020-10-31	58.396 mi
Registration #10	2020-10-31	58.396 mi
Registration #11	2020-10-31	58.396 mi
Registration #12	2020-10-31	58.396 mi
Registration #13	2020-10-31	58.396 mi
Registration #14	2020-10-31	58.396 mi
Registration #15	2020-10-31	58.396 mi
Registration #16	2020-10-31	58.396 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FAEZ079302