

Ford



# General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	White
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



# Internet history

Entry 1

Date Pictures 2021-07-29

31

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #13	2022-06-27 09:00
MOT test number	916322188583
Result	✓ Passed
Next expiry date	2023-06-26

MOT #12	2021-06-26 16:26
MOT test number	384420100716
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))	
Advice Rear Suspension arm pin or bush worn but not resulting in excessive move	ement Both sides trailing
arm (5.3.4 (a) (i))	

MOT #11		2021-06-26 16:26
MOT test number		207928098065
Result		🗙 Failed
<b>Advice</b> Rear Suspension arm (5.3.4 (a) (i))	arm pin or bush worn but not resulting in excessive	movement Both sides trailing
Pass with rectification	Nearside Rear Stop lamp(s) all not working (4.3.1 (	a) (iii))
Advice Front Tyre worn	close to legal limit/worn on edge Both sides (5.2.3 (e	e))

MOT #10	2019-08-26 14:27
MOT test number	595177092047
Result	✓ Passed
Advice Slight play in front joints	

МОТ #9	2018-08-06 11:01
MOT test number	561648063344
Result	✓ Passed
Advice Front Brakes imbalanced requirements only just met. It would	d appear that the braking system

requires adjustment or repair. (1.2.1 (b) (i))





		~~~~~
MOT #8		2018-08-03 16:44
MOT test number		714311417540
Result		🗙 Failed
requires adjustment or repa		raking system
Fail Registration plate in	ncorrect front and rear number plates (0.1 (c))	
MOT #7		2016-11-17 16:46
MOT test number		995832894074
Result		🗸 Passed
МОТ #6		2015-07-04 18:41
MOT test number		587015585192
Result		✓ Passed
MOT #5		2015-07-04 18:41
MOT test number		136255085102
Result		🗙 Failed
Pass with rectification	Nearside Front All position lamps not working (1.1.A.3b)	
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	Offside Windscreen wiper blade insecure (8.2.2)	
Pass with rectification	Offside Front All position lamps not working (1.1.A.3b)	
Pass with rectification	Nearside Windscreen wiper blade insecure (8.2.2)	



MOT #4		2014-05-21 16:35
MOT test number		265701344198
Result		🗙 Failed
Advice Offside Front	yre worn close to the legal limit (4.1.E.1)	
Advice Centre Rear E	khaust has a minor leak of exhaust gases (7.1.2)	
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)	
Advice Nearside Rear	Tyre worn close to the legal limit (4.1.E.1)	

MOT #3		2014-05-21 16:35
MOT test	number	995701444151
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Centre Rear Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2013-04-18 14:04
MOT test number	235588203455
Result	✓ Passed

MOT #1	2012-10-25 13:45
MOT test	number 899539392267
Result	✓ Passed
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		ARMP
Туре		
Damage 2		AMPLE
	E E	AT I
Date		*
Category	AMA	
Туре	No. Contraction of the second s	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-12-03
Last registration	2022-06-27
Complete history	See info



Registration #1	2009-12-03	13 mi
Registration #2	2012-10-25	50.649 mi
Registration #3	2013-04-18	57.264 mi
Registration #4	2014-05-21	82.296 mi
Registration #5	2015-07-04	101.641 mi
Registration #6	2016-11-17	119.495 mi
Registration #7	2018-08-03	123.937 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.227 mi

More info >





# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number CarCheck.co.uk	9K80515 page 11/11