



EJ57EYP

report date: 2024-03-29

General information

Make	FORD
Model	C-MAX TITANIUM TDCI
Colour	Red
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	260 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	58.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-10
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2022-08-08 14:49
MOT test number	908071523988
Result	✓ Passed
Next expiry date	2023-08-07
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Shock absorbers has light misting of oil BOTH SIDES (5.3.2 (b))

MOT #17	2021-01-12 16:15
MOT test number	912390455972
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

MOT #16	2020-12-22 15:24
MOT test number	318432390472
Result	✗ Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	E.m.l on dash
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Nearside Rear Brake calliper clip broken

MOT #15	2019-11-26 14:41
MOT test number	579155621115
Result	✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2019-11-26 14:41

MOT test number

989989227977

Result**✗ Failed****Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2018-12-03 16:23

MOT test number

546851248760

Result**✓ Passed****Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #12**

2018-11-27 11:05

MOT test number

371108837936

Result**✗ Failed****MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #11**

2017-12-04 11:56

MOT test number

202577629657

Result

✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to the legal limit 2.5 mm tread (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit 3 mm tread (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit 3 mm tread (4.1.E.1)

MOT #10

2017-12-04 11:56

MOT test number

181256632062

Result

✗ Failed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Tyre worn close to the legal limit 3 mm tread (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit 3 mm tread (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre worn close to the legal limit 2.5 mm tread (4.1.E.1)

MOT #9

2016-11-04 12:57

MOT test number

494409363921

Result

✓ Passed

**MOT #8** 2015-11-06 11:36**MOT test number** 696074031392**Result** ✓ Passed**MOT #7** 2015-11-04 11:58**MOT test number** 902225219107**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #6** 2014-10-31 14:38**MOT test number** 476584204323**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-10-30 12:12**MOT test number** 435803904367**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-11-01 12:52**MOT test number** 849745703377**Result** ✓ Passed**Notice** Both rear tyres slightly out of shape on inner edges**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2012-11-07 09:21**MOT test number** 205672612344**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-11-16 11:12**MOT test number** 958760621387**Result** ✓ Passed**MOT #1** 2010-10-13 14:33**MOT test number** 322696080260**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-16
Last registration	2022-08-08
Complete history	See info



Registration #1	2007-10-16	18 mi
Registration #2	2010-10-13	38.526 mi
Registration #3	2011-11-16	49.073 mi
Registration #4	2012-11-07	61.152 mi
Registration #5	2013-11-01	74.047 mi
Registration #6	2014-10-30	88.126 mi
Registration #7	2014-10-31	88.126 mi
Registration #8	2015-11-04	101.444 mi
Registration #9	2015-11-06	101.500 mi
Registration #10	2016-11-04	114.104 mi
Registration #11	2016-11-04	114.104 mi
Registration #12	2016-11-04	114.104 mi
Registration #13	2016-11-04	114.104 mi
Registration #14	2016-11-04	114.104 mi
Registration #15	2016-11-04	114.104 mi
Registration #16	2016-11-04	114.104 mi
Registration #17	2016-11-04	114.104 mi
Registration #18	2016-11-04	114.104 mi
Registration #19	2016-11-04	114.104 mi
Registration #20	2016-11-04	114.104 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4473 mm
Wheel base	2640 mm
Kerb weight	1410 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

7J34878