



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT LIFE
Colour	Silver
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-18
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-12
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	33
Total items failed	8

MOT #19	2023-09-01 10:28
MOT test number	600822408611
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #18	2023-08-21 15:31
MOT test number	678378857951
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
MAJOR	Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #17**

2022-08-24 10:58

MOT test number

622549077370

Result

✓ Passed

- Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Minor** Offside Rear Stop lamp(s) obviously incorrectly positioned (4.3.3 (a) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Central Exhaust mounting defective x2 (6.1.2 (a))

MOT #16

2021-08-31 08:25

MOT test number

129461311969

Result

✓ Passed

- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Power steering component has slight seepage from a component (2.1.5 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15

2020-09-09 15:14

MOT test number

563853105352

Result

✓ Passed

MOT #14

2020-09-02 10:59

MOT test number

158622488075

Result

✗ Failed

- MAJOR** Emissions not tested (8.2.1.2 (d))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #13** 2019-08-19 13:09**MOT test number** 879995923984**Result** ✓ Passed**MOT #12** 2019-08-19 13:09**MOT test number** 985102053618**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #11** 2018-08-17 08:07**MOT test number** 427311455037**Result** ✓ Passed**Advice** Nearside Front Power steering component has slight seepage from a component steering rack gaiter (2.1.5 (a))**Advice** Brake pipe corroded, covered in grease or other material both front to rear pipes (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2017-08-22 07:42**MOT test number** 698806344576**Result** ✓ Passed**Advice** Brake pipe slightly corroded offside & nearside front to rear (3.6.B.2c)**Advice** Power steering component(s) has slight seepage from a component nearside steering rack end (2.3.3b)**Advice** Nearside front tyre has a perished outer sidewall**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #9** 2016-08-23 12:34**MOT test number** 686344414655**Result** ✓ Passed**Advice** Brake pipe slightly corroded offside front to rear (3.6.B.2c)**MOT #8** 2015-08-18 09:20**MOT test number** 265780735249**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2014-08-22 14:39**MOT test number** 327804434270**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2014-08-21 10:32**MOT test number** 917673234271**Result** ✗ Failed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Nail in nearside rear tyre**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #5** 2013-08-23 14:34**MOT test number** 785625333240**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #4** 2013-08-23 12:50**MOT test number** 985375433232**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2012-08-18 11:37**MOT test number** 389601732405**Result** ✓ Passed**Notice** Both front tyres slight cracking in tread.**MOT #2** 2011-08-23 12:15**MOT test number** 326195231297**Result** ✓ Passed**MOT #1** 2011-08-23 10:29**MOT test number** 935795531236**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 AF58EZK
Plate since	2019-09-29
Current registration	 AF58EZK
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-12
Last registration	2023-09-01
Complete history	See info



Registration #1	2008-09-12	22 mi
Registration #2	2011-08-23	40.688 mi
Registration #3	2011-08-23	40.688 mi
Registration #4	2012-08-18	50.264 mi
Registration #5	2013-08-23	58.302 mi
Registration #6	2013-08-23	58.302 mi
Registration #7	2014-08-21	67.308 mi
Registration #8	2014-08-22	67.308 mi
Registration #9	2015-08-18	70.928 mi
Registration #10	2016-08-23	76.198 mi
Registration #11	2017-08-22	81.715 mi
Registration #12	2018-08-22	86.232 mi
Registration #13	2019-08-22	90.749 mi
Registration #14	2020-08-22	95.266 mi
Registration #15	2021-08-22	99.783 mi
Registration #16	2022-08-22	104.300 mi
Registration #17	2023-08-22	108.817 mi
Registration #18	2023-08-22	108.817 mi
Registration #19	2023-08-22	108.817 mi
Registration #20	2023-08-22	108.817 mi
Registration #21	2023-08-22	108.817 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1400 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LS0295