



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI SE
Colour	Black
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic


Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	225 g/km
CO2 label	K



**Internet history****Entry 2**

Date	2022-04-12
Pictures	11
Listing price	<a href="#">View report</a>

**source: cargurus.co.uk****Entry 1**

Date	2021-09-24
Pictures	0
Listing price	<a href="#">View report</a>

**source: autotrader.co.uk**



MOT history

MOT expiry date	2025-04-11
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	21
Total items failed	0

MOT #9	2024-04-06 06:59
MOT test number	191725437252
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Outer edge and sidewall (5.2.3 (d) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

**MOT #8**

2024-03-28 12:55

**MOT test number**

928633425473

**Result****✗ Failed****Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**MAJOR** Offside Front Headlamp levelling device inoperative (4.1.5 (a))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Outer edge and sidewall (5.2.3 (d) (ii))**MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #7**

2023-03-24 14:50

**MOT test number**

252362051060

**Result****✓ Passed****MOT #6**

2022-04-12 08:56

**MOT test number**

843546526830

**Result****✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5**

2021-09-24 14:41

**MOT test number**

471641384859

**Result****✓ Passed**

**MOT #4** 2021-02-12 10:12**MOT test number** 200717330874**Result** ✓ Passed**Advice** NSR lamp damaged**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #3** 2021-02-11 13:06**MOT test number** 606110505057**Result** ✗ Failed**MAJOR** Central Rear Seat belt pretensioner missing where fitted as original equipment (7.1.4 (a))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** NSR lamp damaged**MOT #2** 2019-12-04 10:50**MOT test number** 647044632224**Result** ✓ Passed**MOT #1** 2019-12-03 15:42**MOT test number** 725246335344**Result** ✗ Failed**DANGEROUS** Tyre tread depth below requirements of 1.6mm ALL 4 TYRES (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
11 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	368
<b>MOT expiry date</b>	11 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>ET16YZK</b>
Plate since	2024-03-29
Current registration	<b>ET16YZK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-06-30
Last registration	2024-04-06
Complete history	<a href="#">See info</a>



Registration #1	2016-06-30	28 mi
Registration #2	2019-12-03	37.217 mi
Registration #3	2019-12-04	37.230 mi
Registration #4	2021-02-11	45.581 mi
Registration #5	2021-02-12	45.581 mi
Registration #6	2021-09-24	45.880 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2022-05-20	55.277 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2022-05-20	55.277 mi
Registration #11	2022-05-20	55.277 mi
Registration #12	2024-04-06	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2248 kg
Max. allowed weight	3070 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBG021308