




report date: 2024-03-29

General information

Make	NISSAN
Model	350 Z V6
Colour	Silver
Year of manufacture	2004
Top speed	155 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.5 mpg
Consumption extra urban	32.5 mpg
Consumption combined	24.1 mpg
CO2 emission	273 g/km
CO2 label	M







Internet history

Entry 1

Date	2021-12-04
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	30
Total items failed	14

MOT #24 2023-12-22 16:16

MOT test number 799657928220

Result ✓ Passed

Next expiry date 2024-12-21

Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))

MOT #23 2022-12-10 10:55

MOT test number 454248198942

Result ✓ Passed**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Both rear wheel arches have slight corrosion**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #22 2021-12-03 11:56

MOT test number 690271646559

Result ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21** 2020-12-15 14:08**MOT test number** 512585836261**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #20** 2019-10-18 10:20**MOT test number** 196800770301**Result** ✓ Passed**MOT #19** 2019-10-18 08:54**MOT test number** 687062878099**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #18** 2018-10-22 13:52**MOT test number** 719408959121**Result** ✓ Passed**MOT #17** 2018-01-17 09:16**MOT test number** 249029286286**Result** ✓ Passed

**MOT #16**

2018-01-06 09:35

MOT test number

911047873916

Result

✗ Failed

Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #15**

2017-01-19 08:51

MOT test number

301554743583

Result

✓ Passed

Advice Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin very low (3.5.1g)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14**

2017-01-10 16:30

MOT test number

851701744519

Result

✗ Failed

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin very low (3.5.1g)**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #13**

2016-01-12 15:01

MOT test number

784190320659

Result

✓ Passed

**MOT #12** 2016-01-06 10:27**MOT test number** 697669746970**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #11** 2015-01-12 11:21**MOT test number** 156982515495**Result** ✓ Passed**MOT #10** 2014-01-15 12:53**MOT test number** 918335214026**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-01-15 12:53**MOT test number** 256065814072**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #8** 2013-01-11 13:42**MOT test number** 368131413011**Result** ✓ Passed**MOT #7** 2013-01-11 10:35**MOT test number** 326551613086**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust system has part deteriorated**Fail** Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-01-23 12:46**MOT test number** 166313022417**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2010-10-28 10:52**MOT test number** 812731700326**Result** ✓ Passed**MOT #4** 2009-10-22 10:27**MOT test number** 550785699226**Result** ✓ Passed



MOT #3	2008-10-29 10:21
MOT test number	434163608436
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2008-10-29 10:21
MOT test number	881983408379
Result	✓ Passed

MOT #1	2007-11-08 10:17
MOT test number	542642517372
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
29 February 2024

✓

MOT

Expires:
21 December 2024

Tax status	Expired at 29 February 2024
Days left	61 days too late
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-11-17
Last registration	2023-12-22
Complete history	See info



Registration #1	2004-11-17	13 mi
Registration #2	2007-11-08	33.313 mi
Registration #3	2008-10-29	43.539 mi
Registration #4	2009-10-22	57.483 mi
Registration #5	2010-10-28	73.191 mi
Registration #6	2012-01-23	82.772 mi
Registration #7	2013-01-11	86.972 mi
Registration #8	2013-01-11	86.972 mi
Registration #9	2014-01-15	92.545 mi
Registration #10	2015-01-12	97.943 mi
Registration #11	2016-01-06	103.300 mi
Registration #12	2016-01-12	103.349 mi
Registration #13	2016-01-12	103.349 mi
Registration #14	2016-01-12	103.349 mi
Registration #15	2016-01-12	103.349 mi
Registration #16	2016-01-12	103.349 mi
Registration #17	2016-01-12	103.349 mi
Registration #18	2016-01-12	103.349 mi
Registration #19	2016-01-12	103.349 mi
Registration #20	2016-01-12	103.349 mi
Registration #21	2016-01-12	103.349 mi
Registration #22	2016-01-12	103.349 mi
Registration #23	2016-01-12	103.349 mi
Registration #24	2016-01-12	103.349 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1534 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	161051