





report date: 2024-03-29

General information

Make	HONDA
riake	HONDA
Model	ACCORD I-VTEC EX
Colour	Silver
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 3

Date 2023-11-30

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2022-12-20
------	------------

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

Entry 1

Date 2022-02-16

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-09-19
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	1

MOT #16	2023-09-18 09:51
MOT test number	707628323433
Result	✓ Passed
Next expiry date	2024-09-19

MOT #15		2023-09-16 08:09
MOT test	number	785973991880
Result		X Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR	Brake lever has insufficient reserve travel (1.1.2 (a))	

MOT #14		2022-08-31 14:12
MOT test	number	463373152769
Result		✓ Passed
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriou	usly reducing light output (4.1.4

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2022-08-23 15:03

MOT test number 656186263494

Result × Failed

DANGEROUS Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MAJOR Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt Ball jiont presses into hub (5.3.4 (b) (ii))

MOT #12 2021-08-20 11:42

MOT test number 447304677747

Result ✓ Passed

MOT #11 2021-08-19 13:55

MOT test number 817336944649

Result X Failed

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10 2020-08-27 13:55

MOT test number 363986285727

Result

Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2020-08-27 13:55

MOT test number 355104361789

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8	2019-09-20 16:23
MOT test number	302101652046
Result	✓ Passed
MOT #7	2018-10-18 09:40
MOT test number	336283031247
Result	✓ Passed
MOT #6	2017-10-20 10:32
MOT test number	772968090400
Result	✓ Passed
MOT #5	2016-10-05 14:53
MOT test number	986945037456
Result	✓ Passed
MOT #4	2015-10-06 09:54
MOT test number	146007621199
Result	✓ Passed
NOT #2	2014 10 00 14 12
MOT had word as	2014-10-08 14:13
MOT test number	819121684235
Result	✓ Passed
Notice Nearside front wiper blade torn	
Notice Nearside offside rear tyres starting to split perish	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2		2013-10-11 11:35
MOT test	number	635034383272
Result		✓ Passed
Notice	Slight cracking on all four tyres	
Notice	Offside front wiper blade torn at edges	

MOT #1	2012-10-16 12:44
MOT test number	338110992246
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax expired: 1 February 2024



Expires: 19 September 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

*		
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		A
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		,
Current registration	OK SIZ	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-10-20
Last registration	2023-09-18
Complete history	See info



Registration #1	2009-10-20	21 mi
Registration #2	2012-10-16	5.864 mi
Registration #3	2013-10-11	9.059 mi
Registration #4	2014-10-08	13.106 mi
Registration #5	2015-10-06	16.582 mi
Registration #6	2016-10-05	20.993 mi
Registration #7	2017-10-20	23.829 mi
Registration #8	2018-10-18	26.978 mi
Registration #9	2019-09-20	28.708 mi
Registration #10	2020-08-27	33.574 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1443 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	R20A31162709

CarCheck.co.uk page 13/13