



TOYOTA



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | TOYOTA |
| Model | MR2 ROADSTER |
| Colour | Silver |
| Year of manufacture | 2002 |
| Top speed | 130 mph |
| 0 - 60 mph | 7.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 170 Nm at 4.400 rpm |
| Engine capacity | 1.794 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.0 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 178 g/km |
| CO2 label | I |





Internet history

Entry 3

Date 2021-12-08

Pictures 16

Listing price [View report](#)



source: yesauto.com

Entry 2

Date 2021-10-28

Pictures 17

Listing price [View report](#)



source: autotrader.co.uk

Entry 1

Date 2021-09-27

Pictures 17

Listing price [View report](#)



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-10-29 |
| MOT pass rate | 79 % |
| MOT passed | 15 |
| Failed MOT tests | 4 |
| Total advice items | 16 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #19 | 2022-10-27 15:01 |
| MOT test number | 820113668104 |
| Result | ✓ Passed |
| Next expiry date | 2023-10-29 |

| | |
|-----------------|------------------|
| MOT #18 | 2022-10-26 09:49 |
| MOT test number | 822965952952 |
| Result | ✗ Failed |

- DANGEROUS** Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Nearside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))
- DANGEROUS** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Offside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

| | |
|-----------------|-------------------------------|
| MOT #17 | 2021-10-30 13:33 |
| MOT test number | 308995626345 |
| Result | ✓ Passed |
| Advice | Brake discs slightly corroded |



| | |
|------------------------|------------------|
| MOT #16 | 2018-03-07 13:25 |
| MOT test number | 287928604947 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #15 | 2017-03-10 11:28 |
| MOT test number | 561050986682 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #14 | 2016-03-14 13:08 |
| MOT test number | 573573563244 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #13 | 2015-03-10 10:29 |
| MOT test number | 658139465014 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #12 | 2014-03-05 11:46 |
| MOT test number | 259714264013 |
| Result | ✓ Passed |
| <div>Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div>Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> | |

| | |
|------------------------|------------------|
| MOT #11 | 2013-03-05 14:33 |
| MOT test number | 196264463092 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #10 | 2012-03-15 09:49 |
| MOT test number | 168005172079 |
| Result | ✓ Passed |
| <div>Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div> | |

**MOT #9** 2012-03-14 16:11**MOT test number** 496194272077**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #8** 2011-03-09 09:27**MOT test number** 467038561046**Result** ✓ Passed**MOT #7** 2011-03-07 14:16**MOT test number** 415366461066**Result** ✗ Failed**Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)**MOT #6** 2010-03-03 09:24**MOT test number** 453602860075**Result** ✓ Passed**MOT #5** 2009-03-03 12:41**MOT test number** 313182569015**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)

**MOT #4** 2009-03-03 12:41**MOT test number** 433462369080**Result** ✗ Failed**Pass with rectification** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**MOT #3** 2008-03-07 09:17**MOT test number** 301097868095**Result** ✓ Passed**MOT #2** 2007-03-05 09:54**MOT test number** 934194767040**Result** ✓ Passed**MOT #1** 2006-02-24 09:55**MOT test number** 283835856082**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | ME02RXG |
| Plate since | 2019-09-28 |
| Current registration | ME02RXG |
| Plate since | 2019-09-28 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2002-03-28 |
| Last registration | 2022-10-27 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2002-03-28 | 26 mi |
| Registration #2 | 2006-02-24 | 22.596 mi |
| Registration #3 | 2007-03-05 | 29.241 mi |
| Registration #4 | 2008-03-07 | 33.174 mi |
| Registration #5 | 2009-03-03 | 35.667 mi |
| Registration #6 | 2010-03-03 | 37.657 mi |
| Registration #7 | 2011-03-07 | 41.501 mi |
| Registration #8 | 2011-03-09 | 41.501 mi |
| Registration #9 | 2012-03-14 | 45.505 mi |
| Registration #10 | 2012-03-15 | 45.510 mi |
| Registration #11 | 2013-03-05 | 47.704 mi |
| Registration #12 | 2013-03-05 | 47.704 mi |
| Registration #13 | 2013-03-05 | 47.704 mi |
| Registration #14 | 2013-03-05 | 47.704 mi |
| Registration #15 | 2013-03-05 | 47.704 mi |
| Registration #16 | 2013-03-05 | 47.704 mi |
| Registration #17 | 2013-03-05 | 47.704 mi |
| Registration #18 | 2013-03-05 | 47.704 mi |
| Registration #19 | 2013-03-05 | 47.704 mi |
| Registration #20 | 2013-03-05 | 47.704 mi |
| Registration #21 | 2013-03-05 | 47.704 mi |
| Registration #22 | 2013-03-05 | 47.704 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1695 mm |
| Height | 1250 mm |
| Length | 3895 mm |
| Wheel base | 2450 mm |
| Max. allowed weight | 1225 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of axles | 2 |
| Engine number | 1ZZ1045625 |