



report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------|
| Make | VOLKSWAGEN |
| Model | CADDY C20 LWB CDV 104TDI PD |
| Colour | White |
| Year of manufacture | 2009 |
| Top speed | 102 mph |
| 0 - 60 mph | 14.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 103 BHP |
| Max. torque | 250 Nm at 1.900 rpm |
| Engine capacity | 1.896 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 36.7 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 44.8 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-06 |
| Pictures | 1 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-03-07 |
| MOT pass rate | 92 % |
| MOT passed | 11 |
| Failed MOT tests | 1 |
| Total advice items | 19 |
| Total items failed | 1 |

| | |
|------------------|---|
| MOT #12 | 2023-03-08 14:54 |
| MOT test number | 633920153701 |
| Result | ✓ Passed |
| Next expiry date | 2024-03-07 |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |

| | |
|-----------------|---|
| MOT #11 | 2023-03-08 12:32 |
| MOT test number | 209539242257 |
| Result | ✗ Failed |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |
| Fail | Windscreen washer not working (3.5 (a)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii)) |

**MOT #10** 2022-01-21 15:46**MOT test number** 650140745789**Result** ✓ Passed**MOT #9** 2021-06-24 07:50**MOT test number** 608039913221**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-06-30 16:19**MOT test number** 741460050308**Result** ✓ Passed**MOT #7** 2019-07-02 15:06**MOT test number** 776083967199**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened faces (1.1.14 (a) (ii))**Advice** Front tyres wearing smooth inner edges**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Inner Brake pad(s) wearing thin look low?? (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive leaks (8.4.1 (a) (i))**Advice** Front sills have jacking damage**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))



| | |
|---------------|------------------|
| MOT #6 | 2018-07-03 06:54 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 220808098207 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2017-06-28 06:51 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 477174468996 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2016-07-04 10:18 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 974935227226 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2015-06-17 11:56 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 256348665425 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2014-07-01 15:10 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 438962884170 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|---|
| Advice | Front registration plate deteriorated but not likely to be misread (6.3.1d) |
|---------------|---|

| | |
|---------------|------------------|
| MOT #1 | 2012-09-25 16:52 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 756639062262 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✕
Untaxed

Tax expired:
1 April 2024

✕
MOT

Expired:
7 March 2024

Tax status

Expired at 1 April 2024

Days left

29 days too late

MOT expiry date

7 March 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  RO590KZ |
| Plate since | 2019-06-29 |
| Current registration |  RO590KZ |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2009-10-05 |
| Last registration | 2023-03-08 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-10-05 | 17 mi |
| Registration #2 | 2012-09-25 | 92.591 mi |
| Registration #3 | 2014-07-01 | 107.390 mi |
| Registration #4 | 2015-06-17 | 115.882 mi |
| Registration #5 | 2016-07-04 | 125.373 mi |
| Registration #6 | 2017-06-28 | 142.005 mi |
| Registration #7 | 2018-07-03 | 166.330 mi |
| Registration #8 | 2019-06-28 | 181.277 mi |
| Registration #9 | 2020-06-28 | 196.224 mi |
| Registration #10 | 2021-06-28 | 211.171 mi |
| Registration #11 | 2022-06-28 | 226.118 mi |
| Registration #12 | 2023-03-08 | 241.065 mi |
| Registration #13 | 2024-03-29 | 256.012 mi |
| Registration #14 | 2025-03-29 | 270.959 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|--------|---------|
| Width | 2062 mm |
| Length | 4875 mm |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 2 |
| Engine number | BLS 579359 |