



report date: 2022-08-08

## General information

Make	FORD
Model	FIESTA STYLE
Colour	Blue
Year of manufacture	2009
Top speed	104 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





## MOT history

MOT expiry date	2023-12-20
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	13
Total items failed	7

MOT #15 2022-12-21 10:31

MOT test number 739488159565

Result ✓ Passed

Next expiry date 2023-12-20

**Advice** Front Exhaust has a minor leak of exhaust gases flexible joint (6.1.2 (a))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #14 2022-12-08 12:45

MOT test number 686184234749

Result ✗ Failed

**Fail** Rear Inner Integral body structure is fractured and structural rigidity is significantly reduced both sills (6.1.1 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Front Exhaust has a minor leak of exhaust gases flexible joint (6.1.2 (a))

MOT #13 2021-09-28 15:32

MOT test number 939803366708

Result ✓ Passed

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Front Exhaust has a minor leak of exhaust gases flexible joint (6.1.2 (a))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12** 2021-09-28 10:38**MOT test number** 383051807496**Result** ✗ Failed**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Exhaust has a minor leak of exhaust gases flexible joint (6.1.2 (a))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2020-09-05 10:29**MOT test number** 131340432139**Result** ✓ Passed**MOT #10** 2020-09-04 15:26**MOT test number** 558294162677**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))**Fail** Offside Front Brake pipe leaking on an air braking system (1.1.11 (b) (i))**MOT #9** 2019-09-21 11:36**MOT test number** 228667404108**Result** ✓ Passed**MOT #8** 2018-09-29 15:12**MOT test number** 163804471769**Result** ✓ Passed

**MOT #7** 2018-09-28 11:07**MOT test number** 858788908270**Result** ✗ Failed**Fail** Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords both (5.2.3 (d) (i))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #6** 2017-09-25 10:10**MOT test number** 831819254014**Result** ✓ Passed**MOT #5** 2016-09-19 12:04**MOT test number** 847688311037**Result** ✓ Passed**Advice** Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement both (2.4.G.2)**MOT #4** 2015-09-21 12:24**MOT test number** 480830143294**Result** ✓ Passed**MOT #3** 2014-09-18 11:25**MOT test number** 208451864208**Result** ✓ Passed**MOT #2** 2013-09-16 11:37**MOT test number** 515719853299**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2012-09-13 10:23
MOT test number	186517152200
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 January 2024

X

MOT

Expired:  
20 December 2023

Tax status	Expired at 1 January 2024
Days left	88 days too late
MOT expiry date	20 December 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



## Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

### Damage 1

Date	
Category	
Type	

### Damage 2

Date	
Category	
Type	



### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

## Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-08-29
Current registration	 *****
Plate since	2019-08-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	16
<b>First mileage registration</b>	2009-09-23
<b>Last registration</b>	2022-12-21
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2009-09-23	21 mi
<b>Registration #2</b>	2012-09-13	15.961 mi
<b>Registration #3</b>	2013-09-16	20.659 mi
<b>Registration #4</b>	2014-09-18	25.760 mi
<b>Registration #5</b>	2015-09-21	31.043 mi
<b>Registration #6</b>	2016-09-19	35.427 mi
<b>Registration #7</b>	2017-09-25	40.015 mi
<b>Registration #8</b>	2018-09-28	44.156 mi
<b>Registration #9</b>	2019-09-20	48.297 mi
<b>Registration #10</b>	2020-09-18	52.438 mi
<b>Registration #11</b>	2021-09-16	56.579 mi
<b>Registration #12</b>	2022-09-14	60.720 mi
<b>Registration #13</b>	2023-09-12	64.861 mi
<b>Registration #14</b>	2024-09-10	69.002 mi
<b>Registration #15</b>	2025-09-08	73.143 mi
<b>Registration #16</b>	2026-09-06	77.284 mi

**More info** >



## Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

## Safety ratings

NCAP rating



Video

[see crash video](#)



## Dimensions &amp; weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1495 kg

## Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9R85888