





report date: 2024-03-29

General information

Make	CITROEN
Model	SPACETOURER BLUEHDI FLAIR M S/S
Colour	Black
Year of manufacture	2019
Top speed	114 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	370 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2022-02-25	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-05
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #4		2024-03-06 11:46
MOT test	number	894730974858
Result		✓ Passed
Next expiry date 2025-04-0		2025-04-05
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both ((1.1.14 (a) (ii))

MOT #3		2023-04-06 14:51
MOT test	number	248220171528
Result		✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view	w (3.2 (a) (i))

CarCheck.co.uk page 3/11



KN19NLC

report date: 2024-03-29

MOT #2 2023-04-06 14:19 162320604981 **MOT** test number Result × Failed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **MAJOR** Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

MOT #1 2022-04-04 12:03

MOT test number 124589493900

Result ✓ Passed

CarCheck.co.uk page 4/11



See MOT history

Tax & MOT check

Tax expired: 1 June 2023



Expires: 5 April 2025



Tax status	Expired at 1 June 2023
Days left	334 days too late
MOT expiry date	5 April 2025

Tax calculation

Full MOT history

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



KN19NLC

report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

•		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-04-02
Last registration	2024-03-06
Complete history	See info



Registration #1	2019-04-02	15 mi
Registration #2		11.777 es
Registration #3	2022-04-04	35.283 mi
Registration #4		D.777 es
Registration #5		11.777 es
Designation #6		

Registration #6

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	87%
Children	91%
Pedestrian	64%
Safety systems	78%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	2204 mm
Height	1890 mm
Length	4959 mm
Wheel base	3275 mm
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	DY1M4008890

CarCheck.co.uk page 11/11