



report date: 2024-11-06

General information

Make	MINI
Model	COUNTRYMAN COOPER S COOPER S ALL4
Colour	Blue
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-25
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-05-30
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	14
Total items failed	7

MOT #16 2024-05-01 09:08

MOT test number 995410335746

Result ✔ Passed

Next expiry date 2025-05-30

- Advice** Oil leak, but not excessive rocker cover (8.4.1 (a) (i))
- Advice** Offside Front Macpherson strut top bush or bearing has wear or free play, although not excessive
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive sump gasket (8.4.1 (a) (i))
- Advice** Nearside Front Macpherson strut top bush or bearing has wear or free play, although not excessive
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15 2023-05-31 12:40

MOT test number 591094378590

Result ✔ Passed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #14 2023-05-31 09:07

MOT test number 746479640582

Result ✗ Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13 2022-06-21 10:11

MOT test number 319039693214

Result ✓ Passed

MOT #12 2021-07-13 11:41

MOT test number 344410038371

Result ✓ Passed

MOT #11 2020-11-09 14:00

MOT test number 697557543405

Result ✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #10 2019-11-13 11:19

MOT test number 785420896584

Result ✓ Passed

MOT #9 2019-11-12 16:38

MOT test number 500730709306

Result ✗ Failed

Fail Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))



MOT #8	2018-09-24 07:36
MOT test number	205661228963
Result	✓ Passed
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7	2017-09-29 13:52
MOT test number	860951980295
Result	✓ Passed

MOT #6	2017-09-29 08:34
MOT test number	746465567277
Result	✗ Failed
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #5	2016-09-12 14:06
MOT test number	416658319533
Result	✓ Passed

MOT #4	2016-09-12 14:06
MOT test number	102378872918
Result	✗ Failed
Pass with rectification	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3	2015-09-28 10:39
MOT test number	618394883455
Result	✓ Passed



MOT #2	2015-09-22 12:26
MOT test number	600752602608
Result	✗ Failed
Fail	Headlamp cleaning device inoperative (1.7.2)

MOT #1	2014-09-12 09:34
MOT test number	647775554220
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed

Tax due:
1 July 2025

✓
MOT

Expires:
30 May 2025

Tax status	Valid until 1 July
Days left	204
MOT expiry date	30 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	KV61YTU
Plate since	2019-09-29
Current registration	KV61YTU
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-29
Last registration	2024-05-01
Complete history	See info



Registration #1	2011-09-29	11 mi
Registration #2	2014-09-12	18.952 mi
Registration #3	2015-09-22	29.566 mi
Registration #4	2015-09-28	29.811 mi
Registration #5	2016-09-12	43.332 mi
Registration #6	2016-09-12	43.332 mi
Registration #7	2017-09-29	53.497 mi
Registration #8	2017-09-29	53.497 mi
Registration #9	2018-09-24	61.456 mi
Registration #10	2019-09-29	61.456 mi
Registration #11	2019-09-29	61.456 mi
Registration #12	2019-09-29	61.456 mi
Registration #13	2019-09-29	61.456 mi
Registration #14	2019-09-29	61.456 mi
Registration #15	2019-09-29	61.456 mi
Registration #16	2019-09-29	61.456 mi
Registration #17	2019-09-29	61.456 mi
Registration #18	2019-09-29	61.456 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1390 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	B228J007