



report date: 2024-03-28

General information

Make	FIAT
Model	GRAND PUNTO T-JET SPORTING
Colour	White
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	206 Nm at 1.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg





Internet history

Entry 2

Date	2021-07-04
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-03
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #18	2023-09-26 10:57
MOT test number	487499851261
Result	✓ Passed
Next expiry date	2024-10-02
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Noise from engine auxiliary area
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #17	2022-10-03 15:48
MOT test number	272216761028
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16	2022-10-03 09:28
MOT test number	997014187734
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
DANGEROUS	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2021-09-03 14:35
MOT test number	522153334501
Result	✓ Passed

**MOT #14** 2021-08-23 14:15**MOT test number** 422788607974**Result** ✗ Failed**MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**DANGEROUS** Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2020-09-11 15:12**MOT test number** 858030009412**Result** ✓ Passed**MOT #12** 2020-09-10 08:54**MOT test number** 387275598831**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Shock absorbers has a serious fluid leak both rear and offside front (5.3.2 (b))**MAJOR** Offside Rear Upper Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2019-09-13 13:52**MOT test number** 345946313945**Result** ✓ Passed**Advice** Exhaust back box corroded**Advice** Front registration plate delaminated unlikely to be misread**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #10** 2019-09-13 07:47**MOT test number** 273089162439**Result** ✗ Failed**Advice** Exhaust back box corroded**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Front registration plate delaminated unlikely to be misread**MOT #9** 2018-09-07 07:52**MOT test number** 430106311928**Result** ✓ Passed**Advice** Exhaust back box corroded**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #8** 2018-09-07 07:52**MOT test number** 578427260645**Result** ✗ Failed**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Exhaust back box corroded

**MOT #7** 2017-09-04 15:34**MOT test number** 449805124917**Result** ✓ Passed**Advice** REAR EXHAUST BOX CORRODED**Advice** REAR EXHAUST BOX CORRODED**Advice** REAR EXHAUST BOX CORRODED**MOT #6** 2016-09-08 07:51**MOT test number** 388061876135**Result** ✓ Passed**Advice** EXHAUST SILENCER CORRODED**MOT #5** 2015-08-06 16:39**MOT test number** 577928215264**Result** ✓ Passed**Notice** REAR EXHAUST BOX CORRODED**MOT #4** 2015-08-06 08:57**MOT test number** 495158815279**Result** ✗ Failed**Notice** REAR EXHAUST BOX CORRODED**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #3** 2014-08-14 10:22**MOT test number** 515646224201**Result** ✓ Passed



MOT #2	2013-09-03 11:28
MOT test number	945946043226
Result	✓ Passed
Advice	Nearside Rear wheel bearing has slight play (2.6.2)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2012-08-31 12:59
MOT test number	317064142473
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	YX59UTG
Plate since	2019-09-28
Current registration	YX59UTG
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-04
Last registration	2023-09-26
Complete history	See info



Registration #1	2009-09-04	11 mi
Registration #2	2012-08-31	19.956 mi
Registration #3	2013-09-03	25.666 mi
Registration #4	2014-08-14	33.817 mi
Registration #5	2015-08-06	40.223 mi
Registration #6	2015-08-06	40.223 mi
Registration #7	2016-09-08	47.728 mi
Registration #8	2017-09-04	54.661 mi
Registration #9	2018-09-07	61.594 mi
Registration #10	2018-09-07	61.594 mi
Registration #11	2019-09-13	67.324 mi
Registration #12	2020-09-20	73.054 mi
Registration #13	2021-09-20	78.784 mi
Registration #14	2022-09-20	84.514 mi
Registration #15	2023-09-26	90.244 mi
Registration #16	2023-09-26	90.244 mi
Registration #17	2023-09-26	90.244 mi
Registration #18	2023-09-26	90.244 mi
Registration #19	2023-09-26	90.244 mi
Registration #20	2023-09-26	90.244 mi
Registration #21	2023-09-26	90.244 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	1427416