



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-31
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	23
Total items failed	8

MOT #15 2023-10-24 11:40

MOT test number 724171060071

Result ✓ Passed

Next expiry date 2024-11-08

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2022-11-08 11:34

MOT test number 994231349460

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Play in steering rack inner joint(s)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13 2021-11-09 08:47

MOT test number 592472577837

Result ✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

**MOT #12** 2021-11-06 11:11**MOT test number** 569524418194**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #11** 2021-04-09 07:43**MOT test number** 760483059851**Result** ✓ Passed**MOT #10** 2020-10-15 12:49**MOT test number** 448652969399**Result** ✓ Passed**Advice** Rear exhaust box poor condition**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #9** 2020-10-15 10:04**MOT test number** 624141700461**Result** ✗ Failed**Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear exhaust box poor condition

**MOT #8** 2019-10-10 08:06**MOT test number** 357333865740**Result** ✓ Passed**Advice** Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**MOT #7** 2019-10-09 09:37**MOT test number** 882683915925**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-10-05 09:30**MOT test number** 930459344270**Result** ✓ Passed**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Deterioration of exhaust system back box**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2017-10-04 15:23**MOT test number** 368580095138**Result** ✓ Passed

**MOT #4** 2017-10-04 11:57**MOT test number** 385834818767**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #3** 2016-10-12 09:56**MOT test number** 722732195301**Result** ✓ Passed**MOT #2** 2015-09-16 10:40**MOT test number** 510312116237**Result** ✓ Passed**Advice** O/s/r bumper repaired with tape to cover hole**MOT #1** 2014-09-22 09:35**MOT test number** 546885664293**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
8 November 2024

Tax status		Valid until 1 November
Days left		185
MOT expiry date		8 November 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-29
Current registration	 VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-21
Last registration	2023-10-24
Complete history	See info



Registration #1	2011-09-21	13 mi
Registration #2	2014-09-22	27.161 mi
Registration #3	2015-09-16	33.281 mi
Registration #4	2016-10-12	37.219 mi
Registration #5	2017-10-04	57.575 mi
Registration #6	2017-10-04	57.575 mi
Registration #7	2018-10-05	71.859 mi
Registration #8	2019-10-09	78.099 mi
Registration #9	2019-10-10	78.099 mi
Registration #10	2020-05-20	78.099 mi
Registration #11	2020-05-20	78.099 mi
Registration #12	2020-05-20	78.099 mi
Registration #13	2020-05-20	78.099 mi
Registration #14	2020-05-20	78.099 mi
Registration #15	2020-05-20	78.099 mi
Registration #16	2020-05-20	78.099 mi
Registration #17	2020-05-20	78.099 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1453 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3980582