





report date: 2024-03-29

General information

Make	ТОУОТА
Model	AURIS VVT-I ACTIVE TOURING SPORTS
Colour	Blue
Year of manufacture	2016
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	305 Nm at 4.400 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	67.2 mpg
CO2 emission	81 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-04

Pictures 7

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expire date	2022 06 07
MOT expiry date	2022-06-07
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	14
Total items failed	3

MOT #11	2021-06-08 15:15
MOT test number	314136228374
Result	✓ Passed
Next expiry date	2022-06-07
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1	L.1.14 (a) (ii))

MOT #10		2019-11-20 14:35
MOT test	number	920495146590
Result		✓ Passed
Advice	Nearside rear tyre worn on inner edge	
Advice	Offside Rear Nail in tyre and nail	

MOT #9		2019-11-20 11:10
MOT test	number	215871451736
Result		× Failed
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Offside Rear Nail in tyre and nail	
Advice	Nearside rear tyre worn on inner edge	
MAJOR	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 3/12



LL66DRX

report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2019-10-22 10:02 **MOT** test number 851751617650 Result **X** Failed Nearside Headlamp light intensity severely reduced (4.1.4 (a)) **MAJOR** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice **MAJOR** Offside Headlamp aim too low (4.1.2 (a)) Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords **MAJOR** (5.2.3 (d) (i)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice**

MOT #6	2019-05-20 08:35
MOT test number	172235638962
Result	✓ Passed
MOT #5	2018-11-19 09:55
MOT test number	619966121397
Result	✓ Passed

Result	✓ Passed
MOT #4	2018-11-19 09:55
MOT test number	216204610026
Result	★ Failed
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
Pass with rectification lamps both (4.7.1 (b) (ii))	Front Registration plate lamp inoperative in the case of a single lamp or all

CarCheck.co.uk page 4/12



LL66DRX

report date: 2024-03-29

MOT #3	2018-05-10 10:18
MOT test number	952441310436
Result	✓ Passed
MOT #2	2018-05-10 10:18
MOT test number	542283692791
Result	★ Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2017-11-20 15:10
MOT test number	896400371208
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax statusValid until 1 SeptemberDays left124MOT expiry date7 June 2022Full MOT historySee MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



LL66DRX

report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier meeory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-11-23
Last registration	2021-06-08
Complete history	See info



Registration #1	2016-11-23	24 mi
Registration #2	2017-11-20	61.759 mi
Registration #3	2018-05-10	70.575 mi
Registration #4	2018-05-10	70.575 mi
Registration #5	2018-11-19	94.434 mi
Registration #6	2018-11-19	94.434 mi
Registration #7	2019-05-20	114.960 mi
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1485 mm
Length	4595 mm
Wheel base	2600 mm
Kerb weight	1425 kg
Max. allowed weight	1815 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 12/12

Engine number

2ZRV347806