



AD59VCO

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TDI (80BHP)
Colour	Black
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	195 Nm at 2.200 rpm
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg






Internet history

Entry 1

Date	2021-05-23
Pictures	18
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #15	2023-08-11 14:56
MOT test number	361785282316
Result	✓ Passed
Next expiry date	2024-08-10
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-07-25 16:07
MOT test number	722511180632
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #13**

2022-07-23 11:00

MOT test number

669988007186

Result**✗ Failed**

- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Side repeater missing (4.4.1 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Outer Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Front Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12

2021-05-24 13:54

MOT test number

669750268829

Result**✓ Passed****MOT #11**

2020-05-18 10:34

MOT test number

192198554637

Result**✓ Passed**

**MOT #10**

2019-05-21 17:16

MOT test number

210383752759

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Chip in zone b**MOT #9**

2019-05-21 11:30

MOT test number

532334754549

Result

✗ Failed

Fail Exhaust silencer insecure and corroded (8.1.1 (b) (i))**Advice** Chip in zone b**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #8**

2018-05-19 15:43

MOT test number

232952515552

Result

✓ Passed

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Braking system malfunction lamp on.**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Parking brake lever travel high.**Advice** Exhaust system deteriorated.

**MOT #7** 2018-05-19 10:04**MOT test number** 646122455036**Result** ✗ Failed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Parking brake lever travel high.**Advice** Exhaust system deteriorated.**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Braking system malfunction lamp on.**Fail** Nearside Rear Body has a sharp edge caused by damage Wheel trim (6.1.C.1)**MOT #6** 2017-05-13 10:53**MOT test number** 304087212876**Result** ✓ Passed**MOT #5** 2016-04-07 16:02**MOT test number** 577007360951**Result** ✓ Passed**MOT #4** 2015-05-30 12:08**MOT test number** 326270655110**Result** ✓ Passed**MOT #3** 2014-06-02 14:44**MOT test number** 207763354412**Result** ✓ Passed



MOT #2	2013-11-09 11:35
MOT test number	637893413309
Result	✓ Passed
<div>Notice</div> O/s/f side repeater slightly deteriorated	

MOT #1	2012-11-23 16:21
MOT test number	838728022376
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 AD59VCO
Plate since	2024-03-28
Current registration	 AD59VCO
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-22
Last registration	2023-08-11
Complete history	See info



Registration #1	2009-12-22	8 mi
Registration #2	2012-11-23	36.225 mi
Registration #3	2013-11-09	56.754 mi
Registration #4	2014-06-02	64.010 mi
Registration #5	2015-05-30	72.785 mi
Registration #6	2016-04-07	79.396 mi
Registration #7	2017-05-13	85.232 mi
Registration #8	2018-05-19	92.419 mi
Registration #9	2018-05-19	92.419 mi
Registration #10	2019-05-20	92.419 mi
Registration #11	2019-05-20	92.419 mi
Registration #12	2019-05-20	92.419 mi
Registration #13	2019-05-20	92.419 mi
Registration #14	2019-05-20	92.419 mi
Registration #15	2019-05-20	92.419 mi
Registration #16	2019-05-20	92.419 mi
Registration #17	2019-05-20	92.419 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BNV136712