



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM X TDCI
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	329 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G





MOT history

MOT expiry date	2024-07-07
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	56
Total items failed	9

MOT #212023-07-08 09:38

MOT test number171982014151

Result✓ Passed

Next expiry date2024-07-07

- AdviceOil leak, but not excessive (8.4.1 (a) (i))
- AdviceOffside handbrake performance low
- AdviceOffside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- AdviceNearside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- AdviceRear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29% (1.2.1 (b) (i))
- AdviceRear various suspension components corroded
- AdviceRear Child Seat fitted not allowing full inspection of adult belt
- MinorCentral Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- AdviceOffside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceRear Exhaust has a minor leak of exhaust gases and deteriorated (6.1.2 (a))

**MOT #20**

2023-07-08 09:38

MOT test number

653708969399

Result**✗ Failed**

- Advice** Rear Exhaust has a minor leak of exhaust gases and deteriorated (6.1.2 (a))
- Advice** Offside handbrake performance low
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear various suspension components corroded
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29% (1.2.1 (b) (i))
- Pass with rectification** Offside Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #19

2022-02-19 14:20

MOT test number

527706743276

Result**✓ Passed**

- Advice** Both sides front tyres inner edge worn
- Advice** Rear suspension components corroded but not seriously weakened

**MOT #18** 2022-02-19 14:20**MOT test number** 556297326153**Result** ✗ Failed**Advice** Rear suspension components corroded but not seriously weakened**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Both sides front tyres inner edge worn**MOT #17** 2021-01-21 15:31**MOT test number** 952753186532**Result** ✓ Passed**MOT #16** 2021-01-20 11:17**MOT test number** 104831126712**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush. (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush. (5.3.4 (a) (i))**MAJOR** Offside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #15** 2020-01-29 12:33**MOT test number** 710298641961**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2020-01-27 09:48**MOT test number** 828695379009**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #13** 2019-02-13 09:40**MOT test number** 123513935082**Result** ✓ Passed**Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))**MOT #12** 2018-02-02 16:10**MOT test number** 143431129666**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #11**

2018-01-31 09:40

MOT test number

339187179082

Result

✗ Failed

Fail

Nearside Registration plate lamp not working (1.1.C.1d)

Advice

Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice

Rear Parking brake lever has little reserve travel (3.1.6b)

Fail

Exhaust has a major leak of exhaust gases (7.1.2)

Fail

Brake pipe excessively corroded front to rear (3.6.B.2c)

Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #10

2017-02-06 11:49

MOT test number

685290180146

Result

✓ Passed

Advice

Offside front tyre wearing on inner edge

Advice

Front and rear discs have slight corrosion

MOT #9

2017-02-04 10:33

MOT test number

253671317221

Result

✗ Failed

Fail

Brake pipe excessively corroded both front to back (3.6.B.2c)

Advice

Offside front tyre wearing on inner edge

Advice

Front and rear discs have slight corrosion

MOT #8

2016-02-08 09:51

MOT test number

176901831095

Result

✓ Passed



MOT #7	2015-02-13 10:21
MOT test number	558764945041
Result	✓ Passed
Advice	Brake pipe slightly corroded (3.6.B.2c)

MOT #6	2014-02-13 09:43
MOT test number	636894144023
Result	✓ Passed
Advice	Brake pipe slightly corroded (3.6.B.2c)
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Front brake fluctuating, but not excessively (3.7.B.3)

MOT #5	2013-02-18 10:15
MOT test number	509309143035
Result	✓ Passed
Advice	Brake pipe slightly corroded (3.6.B.2c)

MOT #4	2012-02-13 15:18
MOT test number	406194942012
Result	✓ Passed

MOT #3	2012-02-13 10:00
MOT test number	645164042002
Result	✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



MOT #2	2011-02-21 12:18
MOT test number	517572451065
Result	✓ Passed
<div>Notice N/s/f tyre has cut on outer sidewall</div>	

MOT #1	2010-05-20 14:18
MOT test number	811520640102
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
7 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-05-24
Last registration	2023-07-08
Complete history	See info



Registration #1	2007-05-24	6 mi
Registration #2	2010-05-20	51.700 mi
Registration #3	2011-02-21	60.535 mi
Registration #4	2012-02-13	73.588 mi
Registration #5	2012-02-13	73.589 mi
Registration #6	2013-02-18	83.598 mi
Registration #7	2014-02-13	94.219 mi
Registration #8	2015-02-13	104.526 mi
Registration #9	2016-02-08	115.655 mi
Registration #10	2017-02-04	123.211 mi
Registration #11	2017-02-06	123.220 mi
Registration #12	2018-02-08	134.341 mi
Registration #13	2019-02-08	145.462 mi
Registration #14	2020-02-08	156.583 mi
Registration #15	2021-02-08	167.704 mi
Registration #16	2022-02-08	178.825 mi
Registration #17	2023-02-08	189.946 mi
Registration #18	2024-02-08	201.067 mi
Registration #19	2025-02-08	212.188 mi
Registration #20	2026-02-08	223.309 mi
Registration #21	2027-02-08	234.430 mi
Registration #22	2028-02-08	245.551 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4804 mm
Wheel base	2754 mm
Kerb weight	1587 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6A64541