

Ford



General information

| Make | FORD |
|---------------------|------------------------------|
| Model | RANGER WILDTRAK 4X4 DCB TDCI |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 109 mph |
| 0 - 100 km/h | 10.3 seconds |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 147 kW / 200 HP / 198 BHP |
|-------------------------|---------------------------|
| Max. torque | 470 Nm at 2.750 rpm |
| Engine capacity | 3.198 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 24.8 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 32.1 mpg |
| CO2 emission | 228 g/km |
| CO2 label | L |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-07-14 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-01-25 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 1 |

| MOT #7 | 2024-01-26 11:53 |
|------------------|------------------|
| MOT test number | 873612649729 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-25 |

| MOT #6 | 2023-01-20 15:19 |
|-----------------|------------------|
| MOT test number | 128347404502 |
| Result | ✓ Passed |

| MOT #5 | 2023-01-17 12:38 |
|---|------------------|
| MOT test number | 971441915988 |
| Result | ✓ Passed |
| Advice Front Coil spring corroded both sides (5.3.1 (b) (i)) | |
| Advice Vehicle structure is corroded but structural rigidity is not significantly reduced all over surface rust | |
| (6.1.1 (c) (i)) | |
| Advice Rear springs rusty | |





| MOT #4 | 2022 01 16 15.50 |
|---|--|
| MOT #4 | 2023-01-16 15:50 |
| MOT test number | 245522124717 |
| Result | 🗙 Failed |
| Advice Rear springs rusty | |
| Advice Front Coil spring corroded both sides (5.3.1 (b) (i)) | |
| Advice Vehicle structure is corroded but structural rigidity is not significantly (6.1.1 (c) (i)) | y reduced all over surface rust |
| Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i)) | |
| | |
| MOT #3 | 2022-08-09 12:52 |
| | |
| MOT test number | 711760714275 |
| MOT test number Result | |
| | 711760714275 |
| | 711760714275 |
| Result | 711760714275 ✓ Passed |
| Result MOT #2 | 711760714275 ✓ Passed 2021-08-04 11:21 |
| Result MOT #2 MOT test number | 711760714275 ✓ Passed 2021-08-04 11:21 227709707746 |
| Result MOT #2 MOT test number | 711760714275 ✓ Passed 2021-08-04 11:21 227709707746 |
| Result MOT #2 MOT test number Result | 711760714275 ✓ Passed 2021-08-04 11:21 227709707746 ✓ Passed |



Tax & MOT check

| √ Taxed | ✓ MOT |
|--------------------------|-----------------------------|
| Tax due: 1 April 2025 | Expires: 25 January 2025 |
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 25 January 2025 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|--|-------|
| Date | F | |
| Category | | ARME |
| Туре | | |
| Damage 2 | | AMPLE |
| | E E | |
| Date | | \$ |
| Category | AMP | |
| Туре | No. Contraction of the second se | |

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| In miles |
|------------|
| 9 |
| 2017-11-30 |
| 2024-01-26 |
| See info |
| |



| Registration #1 | 2017-11-30 | 8 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-12-11 | 54.186 mi |
| Registration #3 | | 11.117 esi |
| Registration #4 | 2021-08-04 | 59.882 mi |
| Registration #5 | 2022-08-09 | 64.789 mi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.117 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 86% |
| Pedestrian | 81% |
| Safety systems | 71% |
| Overall rating | 89% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2163 mm |
| Height | 1815 mm |
| Length | 5362 mm |
| Wheel base | 3 mm |
| Kerb weight | 2083 kg |
| Max. allowed weight | 3200 kg |
| Additional information | |
| Fuel tank capacity | 80 |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |