





General information

Make	BMW
Model	X5 XDRIVE30D M SPORT
Colour	Grey
Year of manufacture	2014
Top speed	142 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Entry 2Date2022-07-29Pictures4	
Pictures 4	
Listing price <u>View report</u>	
	1.1
	Like me?









source: cargurus.co.uk

Entry 1	
Date	2021-01-29
Pictures	10
Listing price	View report



source: autoonline.co.uk









MOT history

MOT expiry date	2024-08-04
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #9	2023-08-01 10:05
MOT test number	908511711874
Result	✓ Passed
Next expiry date	2024-08-04
Advice Front Brake disc worn, but not excessively and rear (1.1.14 (a) (i))	
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))	

MOT #8	2022-08-05 08:50
MOT test number	941034473403
Result	✓ Passed

MOT #7	2022-01-20 11:57
MOT test number	449441611657
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

МОТ #6	2021-01-23 14:44
MOT test number	848750271835
Result	✓ Passed





MOT #5	2021-01-22 13:05
MOT test number	374624441773
Result	× Failed
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
МОТ #4	2020-02-17 14:08
MOT test number	362377175382
Result	🗸 Passed
Advice Undertrays fitted	
MOT #3	2019-02-26 16:18
MOT test number	163557544071
Result	✓ Passed
MOT #2	2018-03-14 12:26
MOT test number	610524636441
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Direction indicator has light sources not illuminating, but not m lamp. (1.4.A.2c)	ore than 50% mirror
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.3	1i)
MOT #1	2017-03-17 13:35
MOT test number	766774521359
Result	✓ Passed
	• • • • • •

Advice Nearside Direction indicator damaged, but still visible from a reasonable distance door mirror indicator. (1.4.A.2e)



Tax & MOT check

✓ Taxed	✓ МОТ
Tax due: 1 September 2024	Expires: 4 August 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	4 August 2024
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F the state	
Category		LAMP
Туре		W.
Damage 2	Law .	PLL
Date	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Category	ANG	
Туре	W	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plate	5.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2023-08-01
Complete history	See info



Registration #1	2014-03-31	9 mi
Registration #2	2017-03-17	55.725 mi
Registration #3	2018-03-14	73.956 mi
Registration #4	2019-02-26	91.710 mi
Registration #5	2020-02-17	107.453 mi
Registration #6	2021-01-22	113.514 mi
Registration #7		11.117 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.200 au
Registration #11		11.777 mi





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1938 mm
Height	1762 mm
Length	4886 mm
Wheel base	2933 mm
Kerb weight	2070 kg
Max. allowed weight	2780 kg
Additional information	
Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	30808817