





report date: 2024-03-29

#### General information

| Make                | TOYOTA                         |
|---------------------|--------------------------------|
| Model               | COROLLA VVTI COLOUR COLLECTION |
| Colour              | Silver                         |
| Year of manufacture | 2006                           |
| Top speed           | 115 mph                        |
| 0 - 60 mph          | 12.0 seconds                   |
| Gearbox             | 5 speed Manual                 |

### Engine & fuel consumption

| Power                   | 95 BHP              |
|-------------------------|---------------------|
| Max. torque             | 129 Nm at 4.400 rpm |
| Engine capacity         | 1.398 сс            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 33.6 mpg            |
| Consumption extra urban | 49.6 mpg            |
| Consumption combined    | 42.2 mpg            |
| CO2 emission            | 159 g/km            |
| CO2 label               | G                   |



CarCheck.co.uk page 1/13



# Internet history

#### Entry 1

Date 2022-04-03

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



| B 4   | $\sim$ $-$  |      |        |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic  | tory   |
| 101   | C I         | 1115 | I OI V |
|       | •           |      | ,      |

| MOT expiry date    | 2025-04-18 |
|--------------------|------------|
| MOT pass rate      | 89 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 2          |
| Total advice items | 14         |
| Total items failed | 2          |

| MOT #18  |  | 2024-04-17 11:24   |
|--|--|--------------------|
| MOT test   | number   | 991612844169       |
| Result   |  | ✓ Passed           |
| Next expi  | ry date  | 2025-04-18         |
| Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) |  | ed (5.3.3 (b) (i)) |
| Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))           |  | b) (i))            |
| Advice   | Offside Front Lower Suspension arm corroded but not seriously weakened | (5.3.3 (b) (i))    |

| MOT #17         | 2023-04-17 13:50 |
|-----------------|------------------|
| MOT test number | 680948257355     |
| Result          | ✓ Passed         |

| MOT #16  |   | 2022-04-19 10:08 |
|----------|---|------------------|
| MOT test | number  | 843372355217     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e)) |                  |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge and perished (5.2.3 (e  | ))               |

CarCheck.co.uk page 3/13



✓ Passed

**MOT #15** 2021-07-29 11:29

MOT test number 811108693205

**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing side wall cracking and near limit. (5.2.3 (d) (ii))

Minor Front Headlamp lens slightly defective both front lenses poor condition. (4.1.1 (b) (i))

**MOT #14** 2021-07-28 11:40

MOT test number 456128062596

**Result** X Failed

Fail Offside Front Tyre has ply or cords exposed outer tread (5.2.3 (d) (ii))

Minor Front Headlamp lens slightly defective both front lenses poor condition. (4.1.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing side wall cracking and near limit. (5.2.3 (d) (ii))

MOT #13 2020-08-03 16:02

MOT test number 222481087327

**Result** ✓ Passed

**MOT #12** 2019-07-29 11:07

**MOT test number** 578505216292

370303210232

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Result

Advice Offside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #11** 2018-07-30 10:07

MOT test number 455934802569

Result 

Passed

Minor Front Headlamp lens slightly defective both sides lens going dull (4.1.1 (b) (i))

CarCheck.co.uk page 4/13



MOT #4

Result

**MOT** test number

Pass with rectification

HV06KJY report date: 2024-03-29

2012-07-17 13:21

619669992160

**X** Failed

| MOT #10  | 2017-07-31 11:54 |
|--|------------------|
| MOT test number                                | 100477149458     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #9   | 2016-07-26 11:47 |
| MOT test number                                | 895249707919     |
| Result   | ✓ Passed         |
| Advice Nearside Front tyre wearing outer edge. |                  |
| MOT #8   | 2015-08-03 09:18 |
| MOT test number                                | 255775215234     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #7   | 2014-07-16 17:49 |
| MOT test number                                | 717387894176     |
| Result   | ✓ Passed         |
| MOT #6   | 2013-07-19 16:39 |
| MOT test number                                | 517500103262     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #5   | 2012-07-17 13:21 |
| MOT test number                                | 816919492191     |
| Result   | ✓ Passed         |

CarCheck.co.uk page 5/13

Centre Stop lamp not working (1.2.1b)



| MOT #3          | 2011-07-12 14:36 |
|-----------------|------------------|
| MOT test number | 987993391129     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #2          | 2010-07-19 09:55 |
| MOT test number | 403410100261     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2009-06-29 14:50 |
| MOT test number | 834820589164     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 6/13



## Tax & MOT check



| Tax status       | Valid until 1 April |
|------------------|---------------------|
| Days left        | 338                 |
| MOT expiry date  | 18 April 2025       |
| Full MOT history | See MOT history     |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



| Owner | hictor, |
|-------|---------|
| UWNEI | nisioiv |
|       |         |

| ,  |           |    |
|--|-----------|----|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r  |           | TA |
|  |           |    |
|  |           |    |
|  |           |    |
|  |           |    |
| THE STATE OF THE S |           |    |
|  |           |    |
| ***************************************  |           |    |
|  | More info | >  |
| Plate changes  |           |    |
| See in this check if this TOYOTA had different number plates.  |           |    |
| Number of plates   |           | ,  |
| Current registration   | UK UK     |    |
| Plate since  |           |    |
| Current registration   | NK NE     |    |
| Plate since  |           |    |
|  | More info | >  |

CarCheck.co.uk page 10/13



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 11/13



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 19         |
| First mileage registration | 2006-07-18 |
| Last registration          | 2024-04-17 |
| Complete history           | See info   |



| Registration #1  | 2006-07-18 | 19 mi     |
|------------------|------------|-----------|
| Registration #2  | 2009-06-29 | 7.515 mi  |
| Registration #3  | 2010-07-19 | 10.308 mi |
| Registration #4  | 2011-07-12 | 12.930 mi |
| Registration #5  | 2012-07-17 | 16.480 mi |
| Registration #6  | 2013-07-19 | 18.883 mi |
| Registration #7  | 2014-07-16 | 21.349 mi |
| Registration #8  | 2015-08-03 | 24.708 mi |
| Registration #9  | 2016-07-26 | 31.199 mi |
| Registration #10 | 2017-07-31 | 35.820 mi |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | D.777 es  |
| Registration #19 |            | 11.777 mg |

More info >

CarCheck.co.uk page 12/13



## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1710 mm |
|---------------------|---------|
| Height              | 1475 mm |
| Length              | 4180 mm |
| Wheel base          | 2600 mm |
| Kerb weight         | 1205 kg |
| Max. allowed weight | 1655 kg |

# Additional information

| Fuel tank capacity                | 55 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 13/            |

Number of axles 2

Engine number 4ZZU798028