



TOYOTA

V304ELA

report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS SR
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	154 Nm at 4.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg



**MOT history**

MOT #15	2020-09-14 14:15
MOT test number	127541029382
Result	✓ Passed
Next expiry date	2021-09-17
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2019-09-09 13:45
MOT test number	854369672073
Result	✓ Passed
Advice	Front Lower Both sills very corroded but not near any prescribed areas
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #13	2018-09-12 11:01
MOT test number	917594499560
Result	✓ Passed
Advice	Osf seat belt slow going back
Advice	Hole in nsf seal
Advice	Cut in side wall nsf
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2017-09-15 12:02
MOT test number	367283531488
Result	✓ Passed
Advice	Hole in nsf outer seal body work
Advice	Corrosion under car

**MOT #11** 2016-09-15 11:37**MOT test number** 169825261338**Result** ✓ Passed**Advice** Corrosion under car**Advice** Small hole in outer seal nsf**MOT #10** 2015-09-16 10:25**MOT test number** 783943595254**Result** ✓ Passed**MOT #9** 2014-09-15 12:49**MOT test number** 809758454279**Result** ✓ Passed**Notice** Front brake discs slightly pitted**MOT #8** 2013-09-16 14:49**MOT test number** 719149553248**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Pitting on front discs inside

**MOT #7** 2012-09-17 11:58**MOT test number** 736671762256**Result** ✓ Passed

- Notice** Slight damage to outer wall on nearside front tyre
- Notice** Rear number plate delaminating
- Notice** Offside rear shock absorber damp
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight pitting on front brake discs

MOT #6 2011-09-16 11:48**MOT test number** 308029251402**Result** ✓ Passed

- Notice** Damp around osr shock

MOT #5 2010-09-16 13:49**MOT test number** 183479150295**Result** ✓ Passed**MOT #4** 2009-09-16 11:26**MOT test number** 310149159401**Result** ✓ Passed

- Advice** Nearside Front brake disc slightly pitted (3.5.1h)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Front brake disc slightly pitted (3.5.1h)



MOT #3	2008-09-16 12:46
MOT test number	391230868415
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Front brake disc slightly pitted (3.5.1h)
Advice	Nearside Front brake disc slightly pitted (3.5.1h)

MOT #2	2007-09-17 13:18
MOT test number	324840667420
Result	✓ Passed

MOT #1	2006-09-15 13:33
MOT test number	541648456203
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	1999-09-21
Last registration	2020-09-14
Complete history	See info



Registration #1	1999-09-21	18 mi
Registration #2	2006-09-15	49.483 mi
Registration #3	2007-09-17	51.991 mi
Registration #4	2008-09-16	54.648 mi
Registration #5	2009-09-16	57.166 mi
Registration #6	2010-09-16	60.048 mi
Registration #7	2011-09-16	62.417 mi
Registration #8	2012-09-17	64.277 mi
Registration #9	2013-09-17	65.277 mi
Registration #10	2014-09-17	65.277 mi
Registration #11	2015-09-17	65.277 mi
Registration #12	2016-09-17	65.277 mi
Registration #13	2017-09-17	65.277 mi
Registration #14	2018-09-17	65.277 mi
Registration #15	2019-09-17	65.277 mi
Registration #16	2020-09-14	65.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	7AH338788