



Mercedes-Benz

HY6ITGF

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	VITO 122 CDI DUALINER
Colour	Silver
Year of manufacture	2011
Gearbox	5 speed automatic

Engine & fuel consumption

Power	224 BHP
Max. torque	440 Nm at 1.400 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-13
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-19
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	41
Total items failed	5

MOT #15 2023-05-11 15:37

MOT test number 543869201853

Result ✓ Passed

Next expiry date 2024-05-19

Advice Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #14 2023-05-11 10:51

MOT test number 229804365434

Result ✗ Failed

MAJOR Front Exhaust system insecure bracket broken (6.1.2 (a))

Advice Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

Minor Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Pass with rectification Headlamp aim too low (4.1.2 (a))

MAJOR Offside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #13 2022-05-20 15:15

MOT test number 780141728819

Result ✓ Passed

**MOT #12** 2022-02-22 10:21**MOT test number** 576125731799**Result** ✓ Passed**MOT #11** 2020-07-29 09:53**MOT test number** 662432400838**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Exhaust joining clamps corroded and one rear hanger corroded off .

MOT #10 2020-07-29 09:53**MOT test number** 416477730872**Result** ✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Exhaust joining clamps corroded and one rear hanger corroded off .
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

**MOT #9** 2019-08-19 08:15**MOT test number** 906162254168**Result** ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Rear Exhaust silencer slightly loose middle to rear exhaust clamp missing (8.1.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Exhaust mounting defective bracket corroded and snapped (6.1.2 (a))

MOT #8 2018-08-31 15:21**MOT test number** 401195407997**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front most bush.(Perished) (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view Small chip to n/s of screen. (3.2 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front most bush.(Perished) (5.3.4 (a) (i))

**MOT #7** 2018-08-31 10:31**MOT test number** 382430844356**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Front most bush.(Perished) (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin On 3mm. (1.1.13 (a) (ii))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed Tread on 2mm. (5.2.3 (d) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Front most bush.(Perished) (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view Small chip to n/s of screen. (3.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge On 2mm. (5.2.3 (e))**MAJOR** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))**MOT #6** 2017-08-31 14:52**MOT test number** 899101490957**Result** ✓ Passed**MOT #5** 2017-03-17 09:30**MOT test number** 194721127901**Result** ✓ Passed**MOT #4** 2017-03-16 12:33**MOT test number** 535869280350**Result** ✗ Failed**Fail** Offside Headlamp cleaning device inoperative (1.7.2)**MOT #3** 2016-03-22 12:48**MOT test number** 462165953634**Result** ✓ Passed



MOT #2	2016-03-22 12:48
MOT test number	573218125556
Result	✗ Failed
Pass with rectification	Nearside Rear Direction indicators incorrect colour (1.4.A.2f)
Pass with rectification	Offside Rear Direction indicators incorrect colour (1.4.A.2f)

MOT #1	2015-03-26 13:58
MOT test number	155135885498
Result	✓ Passed
Notice	Outer sill covers/bars fitted obscuring some components
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Notice	Brake fluid level down
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 March
-------------------	---------------------

Days left	305
------------------	-----

MOT expiry date	19 May 2024
------------------------	-------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 HY61TGF
Plate since	2024-03-28
Current registration	 HY61TGF
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-10-05
Last registration	2023-05-11
Complete history	See info



Registration #1	2011-10-05	26 mi
Registration #2	2015-03-26	29.155 mi
Registration #3	2016-03-22	41.462 mi
Registration #4	2016-03-22	41.462 mi
Registration #5	2017-03-16	49.762 mi
Registration #6	2017-03-17	49.781 mi
Registration #7	2017-08-31	53.988 mi
Registration #8	2018-08-31	64.208 mi
Registration #9	2018-08-31	64.208 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	64289041176541