



report date: 2024-03-28

General information

Make	MAZDA
Model	6 D TS
Colour	Grey
Year of manufacture	2010
Top speed	132 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-06
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-11
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	51
Total items failed	9

MOT #15 2022-07-12 16:51

MOT test number 783807948242

Result ✓ Passed

Next expiry date 2023-07-11

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14 2021-07-06 14:24

MOT test number 156012214545

Result ✓ Passed

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened pitted but serviceable (1.1.14 (a) (ii))

Advice Nearside Front Inner Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))

Advice Superficial corrosion on underside but not to excess

**MOT #13**

2021-06-24 19:49

MOT test number

186204447598

Result**✗ Failed**

- MAJOR** Nearside Brake pipe excessively corroded front to rear / rear section (1.1.11 (c))
- MAJOR** Brake performance not tested due to pipe leaking on test (1.2.1 (g))
- Advice** Front undertray insecure
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel both (1.3.1 (a) (i))
- MAJOR** Offside Brake pipe leaking on an air braking system front to rear / at rear (1.1.11 (b) (i))
- MAJOR** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Superficial corrosion on underside but not to excess
- MAJOR** Nearside Rear Service brake grabbing severely (1.2.1 (c))
- MAJOR** Front Service brake excessively binding (1.2.1 (f))
- MAJOR** Offside Rear Anti-roll bar ball joint excessively worn detached (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12

2018-04-05 11:02

MOT test number

799263689245

Result**✓ Passed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** N/s/r tyre cracking
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

**MOT #11**

2018-04-05 08:29

MOT test number

829745255225

Result**✗ Failed**

- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** N/s/r tyre cracking
- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)

MOT #10

2017-04-04 16:35

MOT test number

725927649650

Result**✓ Passed**

- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Oil leak
- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

**MOT #9** 2017-04-04 13:58**MOT test number** 851898767852**Result** ✗ Failed

- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Oil leak

MOT #8 2016-04-06 15:48**MOT test number** 178117001202**Result** ✓ Passed**MOT #7** 2016-04-06 14:11**MOT test number** 872278075400**Result** ✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-03-19 14:06**MOT test number** 355398775086**Result** ✓ Passed

**MOT #5** 2015-03-17 15:16**MOT test number** 389076275030**Result** ✗ Failed**Notice** Offside front wheel bearing not checked due to brake bind**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside front brake binding (3.7.B.1)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2014-04-08 13:56**MOT test number** 925418394034**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-04-08 11:16**MOT test number** 978868494032**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Rear wiper torn**MOT #2** 2013-10-14 11:02**MOT test number** 838697783270**Result** ✓ Passed



MOT #1	2013-03-26 16:42
MOT test number	947165983044
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	SL10KNM
Plate since	2019-09-28
Current registration	SL10KNM
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2022-07-12
Complete history	See info



Registration #1	2010-03-31	16 mi
Registration #2	2013-03-26	49.030 mi
Registration #3	2013-10-14	58.215 mi
Registration #4	2014-04-08	61.878 mi
Registration #5	2014-04-08	61.878 mi
Registration #6	2015-03-17	69.223 mi
Registration #7	2015-03-19	69.224 mi
Registration #8	2016-04-06	80.477 mi
Registration #9	2016-04-06	80.477 mi
Registration #10	2016-04-06	80.477 mi
Registration #11	2016-04-06	80.477 mi
Registration #12	2016-04-06	80.477 mi
Registration #13	2016-04-06	80.477 mi
Registration #14	2016-04-06	80.477 mi
Registration #15	2016-04-06	80.477 mi
Registration #16	2016-04-06	80.477 mi
Registration #17	2016-04-06	80.477 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	R210210531