





# General information

Make	VOLVO
Model	V60 D3 R-DESIGN NAV
Colour	Silver
Year of manufacture	2015
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С







Internet history	
Entry 1	
Date	2021-07-27
Pictures	0
Listing price	View report

source: autotrader.co.uk



# MOT history

MOT expiry date	2024-11-04
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #8	2023-10-11 16:25
MOT test number	739623747110
Result	🗸 Passed
Next expiry date	2024-11-04
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously were (a) (ii))	akened slight pitting (1.1.14
Advice Vehicles internal headlight adjuster altered to recheck lights	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weak (a) (ii))	ened slight pitting (1.1.14

# MOT #7 2023-10-09 16:00 MOT test number 480250102693 Result K Failed Fail Nearside Rear Inner Road wheel badly distorted rim (5.2.2 (c) (i)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened slight pitting (1.1.14 (a) (ii)) Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened slight pitting (1.1.14 (a) (ii))

MOT #6	2022-11-04 13:04
MOT test number	178214312340
Result	✓ Passed





MOT #5	2021-11-05 16:10
MOT test number	666386297290
Result	✓ Passed
MOT #4	2021-03-05 09:44
MOT test number	574357065246
Result	✓ Passed
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
MOT #3	2020-03-23 09:48
MOT test number	330096030310

Result	✓ Passed
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Tyre: worn heavily on inner and outer edges
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Windscreen wiper blade defective smearing (3.4 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Windscreen wiper blade defective smearing (3.4 (b) (i))

MOT #2	2019-03-01 10:49
MOT test number	507122152607
Result	✓ Passed
MOT #1	2010 02 22 12,21

MOI #1	2018-03-23 13:21
MOT test number	592851752446
Result	✓ Passed



WF15BTO report date: 2024-03-28

# Tax & MOT check

✓ Taxed	мот
Tax due: 1 April 2025	<b>Expires:</b> 4 November 2024
Tax status	Valid until 1 April
Days left	336
MOT expiry date	4 November 2024
Full MOT history	<u>See MOT history</u>

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Date	1. the second se
Category	ante
Туре	

### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





# Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-23
Last registration	2023-10-11
Complete history	<u>See info</u>



Registration #1	2015-03-23	28 mi
Registration #2	2018-03-23	33.871 mi
Registration #3	2019-03-01	46.046 mi
Registration #4	2020-03-23	58.867 mi
Registration #5	2021-03-05	65.610 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.317 est

More info >





# Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1640 kg
Max. allowed weight	2180 kg
Additional information	
Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11