



report date: 2024-03-29

General information

| | |
|---------------------|-----------------|
| Make | CITROEN |
| Model | DS3 DSTYLE PLUS |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 120 BHP |
| Max. torque | 160 Nm at 4.200 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.1 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 136 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-23 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-26 |
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 7 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #11 | 2023-05-22 13:10 |
| MOT test number | 223560800394 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-26 |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #10 | 2022-05-26 14:45 |
| MOT test number | 218697047392 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #9 | 2022-05-26 13:34 |
| MOT test number | 607848063505 |
| Result | ✗ Failed |
| MAJOR | Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #8 | 2021-05-27 16:04 |
| MOT test number | 188882817742 |
| Result | ✓ Passed |

**MOT #7** 2020-07-30 07:43**MOT test number** 582919538824**Result** ✓ Passed**MOT #6** 2019-08-08 15:21**MOT test number** 720039542598**Result** ✓ Passed**MOT #5** 2019-08-08 09:06**MOT test number** 792578134310**Result** ✗ Failed**MAJOR** Rear Exhaust system insecure box (6.1.2 (a))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure outer edge (5.2.3 (d) (ii))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure outer edge (5.2.3 (d) (ii))**MOT #4** 2018-08-24 08:21**MOT test number** 354079780324**Result** ✓ Passed**MOT #3** 2017-07-17 10:02**MOT test number** 623110887374**Result** ✓ Passed**MOT #2** 2016-08-19 16:08**MOT test number** 261537354969**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #1 | 2015-08-15 09:19 |
| MOT test number | 695752068615 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 32 |
| MOT expiry date | 26 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2012-09-01 |
| Last registration | 2023-05-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-09-01 | 10 mi |
| Registration #2 | 2015-08-15 | 19.990 mi |
| Registration #3 | 2016-08-19 | 25.903 mi |
| Registration #4 | 2017-07-17 | 29.521 mi |
| Registration #5 | 2018-08-24 | 34.190 mi |
| Registration #6 | 2019-08-08 | 37.988 mi |
| Registration #7 | 2019-08-08 | 37.988 mi |
| Registration #8 | 2019-08-08 | 37.988 mi |
| Registration #9 | 2019-08-08 | 37.988 mi |
| Registration #10 | 2019-08-08 | 37.988 mi |
| Registration #11 | 2019-08-08 | 37.988 mi |
| Registration #12 | 2019-08-08 | 37.988 mi |
| Registration #13 | 2019-08-08 | 37.988 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 71% |
| Pedestrian | 35% |
| Safety systems | 83% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1715 mm |
| Height | 1483 mm |
| Length | 3948 mm |
| Wheel base | 2464 mm |
| Kerb weight | 1147 kg |
| Max. allowed weight | 1554 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | FHCA1665093 |