



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 HDI SX
Colour	Blue
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 2.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	111 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-12-21
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-27
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	23
Total items failed	8

## MOT #17 2024-02-28 09:11

MOT test number 470692160575

Result ✓ Passed

Next expiry date 2025-02-27

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

## MOT #16 2023-09-28 14:32

MOT test number 110305941352

Result ✗ Failed**Fail** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Front Headlamp lens slightly defective both (4.1.1 (b) (i))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #15** 2022-10-06 10:54**MOT test number** 173060375385**Result** ✓ Passed**MOT #14** 2021-09-30 06:51**MOT test number** 473759220504**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Rear exhaust box corroded**MOT #13** 2020-10-07 13:03**MOT test number** 197776913770**Result** ✓ Passed**MOT #12** 2019-09-09 13:44**MOT test number** 420567552877**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-09-09 08:43**MOT test number** 304945694196**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))



<b>MOT #10</b>	2018-09-21 09:54
<b>MOT test number</b>	296432104603
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Minor</b>	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #9</b>	2017-09-25 09:28
<b>MOT test number</b>	414584740058
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Direction indicator slightly discoloured (1.4.A.2f)

<b>MOT #8</b>	2016-09-27 12:03
<b>MOT test number</b>	939219375451
<b>Result</b>	✓ Passed
<b>Advice</b>	MIL lamp on
<b>Advice</b>	Slight knock from front drop links
<b>Advice</b>	NSR bump stop missing

<b>MOT #7</b>	2016-09-14 13:54
<b>MOT test number</b>	283908701802
<b>Result</b>	✗ Failed
<b>Advice</b>	NSR bump stop missing
<b>Fail</b>	Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
<b>Advice</b>	MIL lamp on
<b>Advice</b>	Slight knock from front drop links
<b>Fail</b>	Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



<b>MOT #6</b>	2015-09-09 09:39
---------------	------------------

<b>MOT test number</b>	386839115774
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2014-10-15 12:42
---------------	------------------

<b>MOT test number</b>	365378484204
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2014-10-15 11:03
---------------	------------------

<b>MOT test number</b>	675308584262
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

<b>MOT #3</b>	2012-01-10 10:18
---------------	------------------

<b>MOT test number</b>	486950512048
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-02-09 16:17
---------------	------------------

<b>MOT test number</b>	437840441003
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-09-15 13:36
---------------	------------------

<b>MOT test number</b>	142138050259
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
27 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	27 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-02
Last registration	2024-02-28
Complete history	<a href="#">See info</a>



Registration #1	2007-11-02	8 mi
Registration #2	2010-09-15	8.714 mi
Registration #3	2011-02-09	9.339 mi
Registration #4	2012-01-10	18.552 mi
Registration #5	2014-10-15	20.619 mi
Registration #6	2014-10-15	20.619 mi
Registration #7	2015-09-09	22.005 mi
Registration #8	2016-09-14	22.754 mi
Registration #9	2016-09-27	22.757 mi
Registration #10	2017-09-25	28.005 mi
Registration #11	2019-05-29	28.277 mi
Registration #12	2019-05-29	28.277 mi
Registration #13	2019-05-29	28.277 mi
Registration #14	2019-05-29	28.277 mi
Registration #15	2019-05-29	28.277 mi
Registration #16	2019-05-29	28.277 mi
Registration #17	2019-05-29	28.277 mi
Registration #18	2019-05-29	28.277 mi
Registration #19	2019-05-29	28.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	996 kg
Max. allowed weight	1421 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FDAP1935724