



report date: 2024-03-28

General information

Make	FORD
Model	FIESTA TITANIUM
Colour	Red
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-22
Pictures	33
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-21
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	42
Total items failed	9

MOT #16	2023-05-22 16:17
MOT test number	547710261854
Result	✓ Passed
Next expiry date	2024-05-21
Advice	Gearbox mounting defective

MOT #15	2023-05-22 16:16
MOT test number	864350981598
Result	✗ Failed
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Gearbox mounting defective



MOT #14

2022-05-09 14:39

MOT test number

197990365041

Result		✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside front, offside front and nearside rear road wheels slightly distorted	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Air conditioning pipe damaged but not leaking	
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Exhaust heatshield insecure	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))	

**MOT #13**

2022-05-04 16:10

MOT test number

929032643657

Result**✗ Failed****Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Exhaust heatshield insecure**Advice** Play in steering rack inner joint(s)**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))**Advice** Nearside front, offside front and nearside rear road wheels slightly distorted**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Air conditioning pipe damaged but not leaking**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**MOT #12**

2021-05-05 15:53

MOT test number

246203328765

Result**✓ Passed**

**MOT #11**

2020-11-11 11:33

MOT test number

182068889730

Result

✓ Passed

Advice Exhaust heat shield loose**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Engine rattle on idle**MOT #10**

2019-10-04 11:31

MOT test number

432128647380

Result

✓ Passed

Advice Engine has a rattle on idle**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #9**

2019-10-04 09:20

MOT test number

836625287760

Result

✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Engine has a rattle on idle**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #8** 2018-09-19 16:28**MOT test number** 487967765948**Result** ✓ Passed**Advice** Nearside Rear Tyre is cracking**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2018-09-19 08:44**MOT test number** 193195230087**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre is cracking**MOT #6** 2017-09-07 14:22**MOT test number** 279546547157**Result** ✓ Passed**MOT #5** 2016-09-22 11:06**MOT test number** 854168862189**Result** ✓ Passed**MOT #4** 2015-09-15 09:19**MOT test number** 547075265519**Result** ✓ Passed



MOT #3	2014-09-22 13:07
MOT test number	688735364233
Result	✓ Passed
Notice	Items removed from driver's view prior to test
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)
Notice	Small cuts in offside rear tyre

MOT #2	2014-09-22 09:52
MOT test number	449785464256
Result	✗ Failed
Notice	Items removed from driver's view prior to test
Advice	Nearside Track rod end ball joint has slight play (2.2.B.1f)
Notice	Small cuts in offside rear tyre
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #1	2013-09-11 11:50
MOT test number	757334553260
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-01
Last registration	2023-05-22
Complete history	See info



Registration #1	2010-09-01	12 mi
Registration #2	2013-09-11	34.018 mi
Registration #3	2014-09-22	43.490 mi
Registration #4	2014-09-22	43.490 mi
Registration #5	2015-09-15	50.229 mi
Registration #6	2016-09-22	55.158 mi
Registration #7	2017-09-07	57.618 mi
Registration #8	2018-09-19	59.454 mi
Registration #9	2018-09-19	59.454 mi
Registration #10	2019-09-01	61.317 mi
Registration #11	2019-09-01	61.317 mi
Registration #12	2019-09-01	61.317 mi
Registration #13	2019-09-01	61.317 mi
Registration #14	2019-09-01	61.317 mi
Registration #15	2019-09-01	61.317 mi
Registration #16	2019-09-01	61.317 mi
Registration #17	2019-09-01	61.317 mi
Registration #18	2019-09-01	61.317 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9E63133