





report date: 2024-03-28

General information

Make	MINI
Model	ROADSTER COOPER S
Colour	Black
Year of manufacture	2015
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



N99XND

report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-06

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MC	TC	history	
----	----	---------	--

MOT expiry date	2025-02-09
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	5
Total items failed	5

MOT #8	2024-02-09 17:47
MOT test number	696483762621
Result	✓ Passed
Next expiry date	2025-02-09
Advice Oil leak, but not excessive around sump pan gasket (8.4.1 (a) (i))	

MOT #7	2023-02-04 10:45
MOT test number	138338462318
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #6	2022-02-10 10:25
MOT test number	760675700574
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #5 2022-02-09 15:57

MOT test number 703335760639

Result X Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4 2021-03-06 12:27

MOT test number 652177257729

MOT #3 2020-03-21 10:54

MOT test number 676522722524

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2 2019-03-25 16:53

MOT test number 787467135024

Result ✓ Passed

MOT #1 2018-03-12 12:36

MOT test number 377105429723

Result \rightarrow Passed

Advice Items removed from driver's view prior to test

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

William .	40
Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK ME	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-28
Last registration	2024-02-09
Complete history	See info



Registration #1	2015-03-28	29 mi
Registration #2	2018-03-12	25.217 mi
Registration #3	2019-03-25	30.279 mi
Registration #4	2020-03-21	34.192 mi
Registration #5	2021-03-06	45.051 mi
registration "5	2021 03 00	
Registration #6	2021 03 00	11.777 46
	2021 03 00	77,777 es
Registration #6	2021 03 00	77.777 es 77.777 es 77.777 es
Registration #6 Registration #7	2021 03 00	11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	***
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 11/

Number of axles 2

Engine number A072J893