





report date: 2024-03-29

#### General information

Make	VOLKSWAGEN
Model	CC TDI BLUEMOTION TECHNOLOGY DSG
Colour	Brown
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

#### Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



#### Internet history

#### Entry 3

Date 2021-09-26

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 2

Date	2021-09-24
Pictures	0
Listing price	View report

#### source: heycar.co.uk

#### Entry 1

Date 2021-09-23

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2024-12-13
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	5

MOT #10		2023-12-14 15:51
MOT test	number	760139245845
Result		✓ Passed
Next expiry date 2024-12		2024-12-13
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #9	2023-12-06 1	7:26
MOT test	t number 165454773	3567
Result	<b>★</b> Fa	ailed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i	i))

MOT #8		2022-12-06 15:58
MOT test	number	392151382185
Result		✓ Passed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**MOT** test number

DU64JKZ report date: 2024-03-29

461853159019

MOT #7 2022-11-30 11:34

**MOT test number** 159827401236

**Result** X Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear mounting bush detached from bonding (5.3.4 (a) (i))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear mounting bush detached from bonding (5.3.4 (a) (i))

MOT #6	2021-12-08 15:25
MOT test number	227788591445

Result \sqrt{Passed}

MOT #5 2021-05-06 15:13
MOT test number 156405422483

MOT #4 2020-05-29 10:20

MOT test number 215597310261

Result Passed

MOT #3 2019-05-02 13:39

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



MOT test number

Result

Advice
(a) (i))

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice
(ii))

MOT #1 2017-06-27 13:02

MOT test number 214549312353

Result ✓ Passed

CarCheck.co.uk page 5/12





## Tax & MOT check



MOT

Expires: 13 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	13 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

**Date** 

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov <a href="https://example.com/here">here</a> .	
********	
***************************************	
***************************************	
2000000	
***************************************	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 

More info >


CarCheck.co.uk page 10/12



# Mileage check

Registration #14

Odometer	In kilometers
Mileage registrations	14
First mileage registration	2014-09-05
Last registration	2023-12-14
Complete history	See info



Registration #1	2014-09-05	26 mi
Registration #2	2017-06-27	11.152 mi
Registration #3	2018-06-05	12.922 mi
Registration #4	2019-05-02	13.649 mi
Registration #5	2020-05-29	19.984 mi
Registration #6	2021-05-06	25.970 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	CFFBK81075