



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Black
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.8 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-23
Pictures	26
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #72023-06-26 13:15

MOT test number998773795462

Result✓ Passed

Next expiry date2024-06-25

- Minor

Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #6** 2023-06-26 12:28**MOT test number** 244286821690**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2022-05-25 12:31**MOT test number** 849098897145**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #4** 2021-05-25 10:39**MOT test number** 628459728869**Result** ✓ Passed**MOT #3** 2020-11-17 16:08**MOT test number** 696327491850**Result** ✓ Passed



MOT #2	2020-11-17 07:44
MOT test number	632412925842
Result	✗ Failed
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1	2019-11-09 11:53
MOT test number	475664127808
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	All rear seat belts retract slowly



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	HK66AYX
Plate since	2019-06-29
Current registration	HK66AYX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-25
Last registration	2023-06-26
Complete history	See info



Registration #1	2016-11-25	19 mi
Registration #2	2019-11-09	84.922 mi
Registration #3	2020-11-17	104.278 mi
Registration #4	2020-11-17	104.278 mi
Registration #5	2021-05-25	107.840 mi
Registration #6	2022-05-25	111.377 mi
Registration #7	2022-05-25	111.377 mi
Registration #8	2022-05-25	111.377 mi
Registration #9	2023-06-26	115.000 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	2950 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	R9M MG - C127879LWY