

Ford



General information

MakeFORDModelKA ZETECColourSilverYear of manufacture2010Top speed99 mph0 - 60 mph13.1 secondsGearbox5 speed Manual		
ColourSilverYear of manufacture2010Top speed99 mph0 - 60 mph13.1 seconds	Make	FORD
Year of manufacture 2010 Top speed 99 mph 0 - 60 mph 13.1 seconds	Model	KA ZETEC
Top speed 99 mph 0 - 60 mph 13.1 seconds	Colour	Silver
0 - 60 mph 13.1 seconds	Year of manufacture	2010
	Top speed	99 mph
Gearbox 5 speed Manual	0 - 60 mph	13.1 seconds
	Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С





MOT history

MOT expiry date	2021-01-27
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #12	2020-01-22 16:08
MOT test number	283599527758
Result	✓ Passed
Next expiry date	2021-01-27
Advice Nearside Rear damage to quarter panel	

MOT #11		2019-01-22 11:31
MOT test	number	875317976418
Result		✓ Passed
Advice	Rear exhaust silencer deteriorated	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #10		2019-01-22 11:31
MOT test number		846003101423
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Advice Nearside Front A	nti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Rear exhaust sile	encer deteriorated	
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	





MOT #9	2018-01-25 12:03
MOT test number	228574726443
Result	✓ Passed
Advice Nearside Front Suspension arm rubber bush deteriorated but no rear bush (2.4.G.2)	ot resulting in excessive movement
Advice Rear exhaust silencer corroded	
MOT #8	2018-01-25 08:57

MOT test number	677555738461
Result	🗙 Failed
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in rear bush (2.4.G.2)	excessive movement
Advice Rear exhaust silencer corroded	
Fail Nearside Front Tyre has ply or cords exposed tyre sidewall cut to cords (4.1.D.1b)

MOT #7	2017-01-06 13:43
MOT test number	278433160303
Result	✓ Passed
Advice Rear exhaust corroded	
Advice Rear wiper rubber split	

MOT #6	2017-01-06 11:05
MOT test number	129257330057
Result	🗙 Failed
Advice Rear exhaust corroded	
Advice Rear wiper rubber split	
Fail Offside Front Suspension arm ball joint dust cover excessively damaged so the ingress of dirt (2.4.G.2)	o that it no longer prevents





MOT #5		2016-01-23 08:46
MOT test	number	695884248417
Result		✓ Passed
Advice Offside Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)		preventing the ingress of dirt
MOT #4		2015-01-10 10:50

MOT test ı	number	246170115050
Result		✓ Passed
Advice (2.5.B.1b)	Nearside Front Macpherson strut has slight movement in the upper support	bearing assembly

MOT #3	2014-08-01 16:30
MOT test number	879893314291
Result	✓ Passed

MOT #2	2014-01-20 10:34
MOT test number	506550124037
Result	✓ Passed
Notice Air filter box insecure	

MOT #1	2013-01-16 11:22
MOT test number	816106413099
Result	✓ Passed
Notice Handbrake cable outer split and corroded	



Tax & MOT check

X Untaxed Tax expired: 14 June 2021	X MOT Expired: 27 January 2021
Tax status	Expired at 14 June 2021
Days left	1051 days too late
MOT expiry date	27 January 2021
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	C

Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-01-27
Last registration	2020-01-22
Complete history	See info



Registration #1	2010-01-27	17 mi
Registration #2	2013-01-16	24.589 mi
Registration #3	2014-01-20	37.901 mi
Registration #4	2014-08-01	44.525 mi
Registration #5	2015-01-10	47.674 mi
Registration #6	2016-01-23	51.599 mi
Registration #7	2017-01-06	56.556 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	5775203