



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ3 DDIS
Colour	Red
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2023-07-24
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-05-03
MOT pass rate	50 %
MOT passed	7
Failed MOT tests	7
Total advice items	26
Total items failed	14

MOT #142023-05-03 14:28

MOT test number397561172430

Result✓ Passed

Next expiry date2024-05-03

- Advice

Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge and 2mm Advice change (5.2.3 (e))
- Minor

Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge Advice change soon (5.2.3 (e))
- Minor

Nearside Windscreen wiper blade defective (3.4 (b) (i))



MOT #13	2023-05-03 10:41
MOT test number	708185803860
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge and 2mm Advice change (5.2.3 (e))
Minor	Offside Windscreen wiper blade defective (3.4 (b) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Advice change soon (5.2.3 (e))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #12	2022-05-04 15:13
MOT test number	961648579100
Result	✓ Passed

MOT #11	2022-05-04 13:19
MOT test number	951550460371
Result	✗ Failed
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #10	2020-05-28 12:22
MOT test number	598838143973
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2020-05-28 12:22**MOT test number** 663570386334**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-05-03 10:14**MOT test number** 838176464344**Result** ✓ Passed**MOT #7** 2019-05-03 10:14**MOT test number** 851725925152**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #6** 2018-05-04 11:10**MOT test number** 739311632740**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)

**MOT #5** 2018-05-04 11:10**MOT test number** 808943235208**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)**MOT #4** 2017-05-04 13:52**MOT test number** 328905402450**Result** ✓ Passed**MOT #3** 2017-05-04 12:30**MOT test number** 785884658991**Result** ✗ Failed**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm edge (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #2	2016-05-04 09:15
MOT test number	559472179742
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin 2.5mm (3.5.1g)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner side corroded (3.5.1i)
Advice	Nearside Front Brake pad(s) wearing thin 2.5mm (3.5.1g)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened inner side corroded (3.5.1i)

MOT #1	2016-05-04 09:15
MOT test number	888402014517
Result	✗ Failed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner side corroded (3.5.1i)
Advice	Nearside Front Brake pad(s) wearing thin 2.5mm (3.5.1g)
Pass with rectification	Nearside Stop lamp not working (1.2.1b)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened inner side corroded (3.5.1i)
Advice	Offside Front Brake pad(s) wearing thin 2.5mm (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
3 May 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	3 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-07
Last registration	2023-05-03
Complete history	See info



Registration #1	2012-09-07	21 mi
Registration #2	2016-05-04	30.862 mi
Registration #3	2016-05-04	30.862 mi
Registration #4	2017-05-04	41.346 mi
Registration #5	2017-05-04	41.354 mi
Registration #6	2018-05-04	52.263 mi
Registration #7	2018-05-04	52.263 mi
Registration #8	2019-05-03	60.042 mi
Registration #9	2019-05-03	60.042 mi
Registration #10	2019-05-03	60.042 mi
Registration #11	2019-05-03	60.042 mi
Registration #12	2019-05-03	60.042 mi
Registration #13	2019-05-03	60.042 mi
Registration #14	2019-05-03	60.042 mi
Registration #15	2019-05-03	60.042 mi
Registration #16	2019-05-03	60.042 mi
Registration #17	2019-05-03	60.042 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1170 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	D13A-1595025